



**US Army Corps  
of Engineers®**  
Engineer Research and  
Development Center

## **Airfield Pavement Evaluation, Butts Army Airfield, Fort Carson, Colorado**

Robert W. Grau, Patrick S. McCaffrey, Jr.,  
and Dan D. Mathews

April 2003  
Revised



# Airfield Pavement Evaluation, Butts Army Airfield, Fort Carson, Colorado

Robert W. Grau, Patrick S. McCaffrey, Jr., Dan D. Mathews

*Geotechnical and Structures Laboratory  
U.S. Army Engineer Research and Development Center  
3909 Halls Ferry Road  
Vicksburg, MS 39180-6199*

## Final report

Distribution is limited to U.S. Government agencies only; test and evaluation; April 2003. Other requests for this document shall be referred to Headquarters, U.S. Army Corps of Engineers (CECW-EW), Washington, DC 20314-1000.

Prepared for U.S. Army Forces Command  
ATTN: AFEN-PR  
Fort McPherson, Georgia 30330-1062

**ABSTRACT:** An airfield pavement evaluation was performed in May 2002 at Butts Army Airfield, Fort Carson, Colorado, to develop information pertaining to the structural adequacy of the airfield pavements for continued use under its current mission and the upgrading of the pavements for mission changes. The pavement surface condition was evaluated using the Pavement Condition Index (PCI) survey procedure, and a nondestructive evaluation procedure was used to determine the load-carrying capability of the pavements and overlay requirements for continued use of the pavements under current missions. Results of the evaluation are presented including: (a) a tabulation of the existing pavement features, (b) the results of the nondestructive tests performed using a heavy weight deflectometer, (c) the PCI and rating of the surface of each pavement feature, (d) a structural evaluation and overlay requirements for 6,000 passes of the C-130 aircraft on the fixed-wing pavements and 50,000 passes of the CH-47 aircraft on the rotary-wing pavements, (e) the pavement classification number for each pavement facility, and (f) maintenance and repair recommendations based on the structural evaluation and condition survey.

**DISCLAIMER:** The contents of this report are not to be used for advertising, publication, or promotional purposes. Citation of trade names does not constitute an official endorsement or approval of the use of such commercial products. All product names and trademarks cited are the property of their respective owners. The findings of this report are not to be construed as an official Department of the Army position unless so designated by other authorized documents.

**DESTRUCTION NOTICE:** For classified documents, follow the procedures in DOD 5200.22-M, Industrial Security Manual, Section II-19, or DOD 5200.1-R, Information Security Program Regulation, Chapter IX. For unclassified, limited documents, destroy by any method that will prevent disclosure of contents or reconstruction of the document.

# Contents

---

Preface .....	iv
Executive Summary .....	vi
1—Introduction .....	1
Background .....	1
Objective and Scope .....	1
2—Pavement Load-Carrying Capacity .....	3
General .....	3
Load-Carrying Capacity .....	4
3—Recommendations for Maintenance, Repair, and Structural Improvements ....	6
General .....	6
Recommendations .....	7
4—Conclusions .....	18
References .....	19
Appendix A: Background Data .....	A1
Appendix B: Tests and Results .....	B1
Appendix C: Pavement Condition Survey and Results .....	C1
Appendix D: Structural Analyses .....	D1
Appendix E: Micro PAVER Output Summary .....	E1
SF 298 .....	



# Preface

---

The purpose of this report is to provide an assessment of load-carrying capacity and condition of airfield pavements at Butts Army Airfield (BAAF), Fort Carson, Colorado. This report provides data for the following:

- a.* Planning and programming pavement maintenance, repairs, and structural improvements.
- b.* Designing maintenance, repair, and construction projects.
- c.* Determining airfield operational capabilities.
- d.* Providing information for aviation flight publications and mission planning.

Users of information from this report include the installation's Directorate of Installation Support (DIS), engineering design agencies (DIS's, U.S. Army Corps of Engineers), Airfield Commanders, U.S. Army Aeronautical Services Agency, and agencies assigned operations planning responsibilities. Information concerning aircraft inventory, passes, and operations shall not be released outside U.S. Government agencies. This report satisfies requirements for condition inspection and structural evaluation established in Army Regulation AR 420-72 (Headquarters, Department of the Army 2000) and supports airfield survey requirements identified in Army Regulation AR 95-2 (Headquarters, Department of the Army 1990).

The Army Airfield Pavement Evaluation Program is sponsored and technically monitored by the U.S. Army Corps of Engineers, Transportation Systems Center (CENWO-ED-TX), located in Omaha, NE. The U.S. Army Forces Command, Fort McPherson, Georgia, provided funding for this investigation.

Personnel of the U.S. Army Engineer Research and Development Center (ERDC), Geotechnical and Structures Laboratory (GSL), Vicksburg, MS, prepared this publication. The findings and recommendations presented in this report are based upon pavement structural testing, data analysis, and condition survey work at BAAF. The required field testing was conducted in May 2002. The evaluation team consisted of Messrs. Dan D. Mathews and Andrew Harrison, Airfield and Pavements Branch (APB), GSL. Messrs. Robert W. Grau, Patrick S. McCaffrey, Jr., and Mathews prepared this publication under the

Mr. Don R. Alexander, Chief, APB; Dr. Albert J. Bush III, Chief, Engineering Systems and Materials Division; and Dr. David W. Pittman, Acting Director, GSL.

At the time of publication of this report, COL John W. Morris III, EN, was Commander and Executive Director of ERDC, and Dr. James R. Houston was Director.

Recommended changes for improving this publication in content and/or format should be submitted on DA Form 2028 (Recommended Changes to Publications and Blank Forms) and forwarded to Headquarters, U.S. Army Corps of Engineers, ATTN: CECW-EW, 441 G Street NW, Washington, DC 20314.

# Executive Summary

---

Personnel of the U.S. Army Engineer Research and Development Center (ERDC), Vicksburg, MS, conducted the field testing at Butts Army Airfield (BAAF), Fort Carson, Colorado, during May 2002. The structural capacity and physical properties of the pavement facilities were determined from nondestructive tests using a heavy weight deflectometer (HWD) and from measurements taken in previous studies. A visual inspection was also conducted to establish the condition of the airfield surface, which does not necessarily correspond to its load-carrying capacity.

The results of the tests and visual inspection reveal the following:

- a. The primary airfield pavement facilities and their assigned Pavement Classification Number (PCN) are shown in Illustration 1.
- b. The seven runway features (R1A through R7A), three taxiway features (T2A, T3A, and T6A), and six apron features (A1B, A2B, A3B, A4B, A5B, and A6B) that were considered fixed-wing facilities are structurally inadequate to withstand the projected fixed-wing day-to-day mission (i.e., peacetime use) C-130 traffic. Five of the ten pavement features (T1A, T4B, T5A, A11B, and A12B) that were evaluated for rotary-wing traffic are structurally inadequate to withstand the projected CH-47 traffic.
- c. Although the runway overrun (R1A) and Hoverlane (A3B) were reconstructed in 2001, they are structurally inadequate to withstand the projected traffic.
- d. Installation Status Report (ISR) ratings for the airfield are shown in Illustration 2.
- e. As a result of the very low surface condition ratings of 10 of 11 features failing to meet the minimum Pavement Condition Index (PCI) requirements, repair is recommended for only one feature (T3B). Approximately \$33,500 (FY03) for repair is required to improve the surface of taxiway feature T3B to meet the minimum PCI requirements. M & R is not recommended for features R2A through R6A, T1A, T4B through T6A, and A2B.

- f.* Although the PCI of 10 features (A4B through A13B) meet the minimum PCI requirements, approximately \$400,000 (FY 03) in M & R is recommended.
- g.* In planning structural improvements and/or reconstruction requirements, it should be recognized that UFC 3-260-02 (Headquarters, Departments of the Army, Navy, and the Air Force 2001b) specifies that the following pavements be rigid pavement: all paved areas on which aircraft or helicopters are regularly parked, maintained, serviced, or preflight checked, on hangar floors and access aprons; on runway ends (305 m (1,000 ft) of a Class B runway; primary taxiways for Class B runways; hazardous cargo, power check, compass calibration, warmup, alert, arm/disarm, holding, and washrack pads; and any other area where it can be documented that a flexible pavement will be damaged by jet blast or by spillage of fuel or hydraulic fluid.
- h.* Overloading the pavement facilities may shorten the life expectancy.

Additional details on structural capacity, surface condition, and work required to maintain and strengthen the airfield are contained in Chapters 2 and 3 of this report.




Illustration 1. Airfield Pavement Evaluation Chart (APEC)




Illustration 2. Airfield pavement ISR ratings

# 1 Introduction

---

## Background

In May 1982 the Department of the Army initiated a program to determine and evaluate the physical properties, the load-carrying capacity for various aircraft, and the general condition of the pavements at major U.S. Army Airfields (AAFs). This program was established at the request of the Major Army Commands (FORSCOM, TRADOC, and AMC). Headquarters, U.S. Army Corps of Engineers (CECW-EW) sponsors a program for periodic evaluation of Army Airfield facilities in accordance with Army Regulation AR 420-72 (Headquarters, Department of the Army 2000). All Category 1 AAFs and instrumented U.S. Army Heliports (AHPs) are included in the CECW-EW program. The evaluation of the airfield pavements was performed to determine the structural adequacy of the existing pavements to accommodate mission aircraft. Results of this evaluation were also used to identify maintenance, repair, and major repair work requirements and to help establish Installation Status Report (ISR) ratings. The U.S. Army Forces Command, Fort McPherson, Georgia, provided funding for this investigation. Results of this investigation will provide current information for designing upgrades to the pavement facilities.

## Objective and Scope

The primary objectives of this investigation were to determine the allowable aircraft loads and design traffic, and to identify maintenance, repair, and structural improvement needs for each airfield pavement feature. These objectives were accomplished by:

- a. Obtaining records of day-to-day traffic operations from the installation Airfield Commander.
- b. Conducting a structural evaluation of the airfield pavements in accordance with UFC 3-260-03 (Headquarters, Departments of the Army, Navy, and the Air Force 2001a) using the nondestructive testing device.

- c.* Performing a condition survey to determine pavement distresses (type, severity and magnitude) in accordance with ASTM D 5340-93 and using analysis features of the Micro PAVER pavement management system.

The results of this study can be used to:

- a.* Provide preliminary engineering data for pavement design (Appendixes A and B).
- b.* Assist in identifying and forecasting maintenance and repair work, the preparation of long range work plans, and programming funds for the various work classification categories (Appendixes C and E).
- c.* Determine type and gross weights of aircraft that can operate on a given airfield feature without causing structural damage or shortening the life of the pavement structure (Appendix D).
- d.* Determine aircraft operational constraints as a function of pavement strength and surface condition (Appendix D).
- e.* Determine the need for structural improvements to sustain current levels of aircraft operations (Appendix D).
- f.* Summarize results for ISR ratings (Executive Summary).

Chapter 2 of this report includes the results of the aircraft classification number-pavement classification number (ACN-PCN) analysis for use by U.S. Army Aeronautical Services Agency (USAASA), the airfield commander, and Deputy Chief of Staff for Operations and Plans (DCSOPS) personnel. Chapter 3 contains maintenance, repair, and structural improvement recommendations for use by DPW personnel and design agencies. Chapter 4 contains conclusions and recommendations in summary form. Detailed supporting data are provided in the appendices.




## 2 Pavement Load-Carrying Capacity

---

### General

The load-carrying capacity is a function of the strength of the pavement, the gross weight of the aircraft, and the number of applications of the load. The method used to report pavement load-carrying capacity is the ACN-PCN system as adopted by the International Civil Aviation Organization (ICAO). The United States, as a participating member of ICAO, is required to report pavement strength in this format. The ACN-PCN format also provides the airfield evaluation information required by Army Regulation AR 95-2 (Headquarters, Department of the Army 1990).

The ACN and PCN are defined as follows: The ACN is a number which expresses the relative structural effect of an aircraft on both flexible and rigid pavements for specific standard subgrade strengths in terms of a standard single wheel load. The PCN is a number which expresses the relative load-carrying capacity of a pavement for a given pavement life in terms of a standard single wheel load. An example of a PCN five part code is as follows:



The system works by comparing the ACN to the PCN. The PCN is a representation of the allowable load for a specified number of repetitions over the life

---

<sup>1</sup> Most of the dimensions and measurements reported were obtained in non-SI units. All such values have been converted using the conversion factors given in ASTM E 621.

of a pavement. The ACN is a representation of the load applied by an aircraft using the pavement. The system is structured such that an aircraft operating at an ACN (applied load) equal to or less than the PCN (allowable load) would comply with load restrictions established based on a specified design life for the pavement facility. If, however, the ACN (applied load) is greater than the PCN (allowable load), the specified design life will be shortened due to this overloading. Pavements can usually support some overload; however, pavement life is reduced. As a general rule, ACN/PCN ratios of up to 1.25 have minimal impact on pavement life. If the ACN/PCN ratio is between 1.25 and 1.50, aircraft operations should be limited to 10 passes, and the pavement inspected after each operation. Aircraft operations resulting in an ACN/PCN ratio over 1.50 should not be allowed except for emergencies.

## Load-Carrying Capacity

The first step in determining the load-carrying capacity of the pavements at Butts Army Airfield (BAAF), Fort Carson, Colorado, was to estimate the traffic to which the airfield will be subjected over the next 20 years. The C-130 was considered the design aircraft for the primary airfield fixed-wing facilities; Runway 13-31, Taxiways C and D, 13 and 31 Warm-up areas, the Hoverlane, Transient Parking Ramp, and Charlie Parking Ramp. All AC and PCC fixed-wing pavement facilities were evaluated for 6,000 passes of a C-130. All rotary-wing facilities were evaluated for 50,000 passes of a CH-47. Using this traffic information and results of the data analysis, the ACN value for the critical aircraft operating on the BAAF pavements was determined. The operational ACN for the airfield is 30/R/B/W/T for the rigid pavements and 30/F/C/W/T for the flexible pavements. See Table D5 for description of the five component ACN or PCN code. The numerical ACN values calculated for the critical aircraft operating on AC and PCC pavements on each of the four subgrade categories are presented in Table D2.

The critical PCN value for each airfield facility is presented in the Airfield Pavement Evaluation Chart (APEC) in Illustration 1. A summary of allowable loads and overlay requirements determined for the critical aircraft and its design pass level is shown in Table D3. PCN codes for the controlling feature of each facility are presented in Table D4. The effects of thaw-weakened conditions were considered and the results are summarized in Table D4.

The number of passes of mobilization and contingency aircraft loadings that could be sustained by each facility is dependent on the ACN of the aircraft and the critical PCN of the facility. During wartime, many aircraft are allowed to carry heavier loads than during peacetime. This allowance means that the aircraft would have a higher ACN because of the higher loading and would cause more damage per pass than in peacetime. Also, under some contingency plans or during emergencies, heavier aircraft than design aircraft (C-130) could be considered for using the airfield pavements. These heavier aircraft would generally have higher ACN values and cause more damage than those normally using the airfield. The operational life of the pavement will be reduced if it is subjected to

aircraft loadings having ACN values higher than the PCN of the facility. An example of a procedure to determine the impact of mobilization and contingency aircraft operations is presented in Appendix D.

# 3 Recommendations for Maintenance, Repair, and Structural Improvements

---

## General

Recommendations for maintenance, repair, and structural improvements are based on results from both the structural evaluation (Appendix D) and the pavement condition survey (Appendix C). Either or both the evaluation and/or the survey may indicate that a particular feature needs repair and/or improvement. If the pavement condition index (PCI) is below the required value contained in Army Regulation AR 420-72 (Headquarters, Department of the Army 2000), the pavement needs maintenance to improve its surface condition. If the ACN/ PCN ratio determined for the critical aircraft is greater than one, the pavement needs structural improvement. Where both evaluations indicate improvements are needed, the recommendations are made such that the repairs to the surface are those needed until the structural improvements can be made. If the structural improvements are made first, the surface repairs may not be necessary. The PCI, ACN/PCN, ISR rating, and recommended general maintenance alternatives for each feature are shown in Table 3-1, the Airfield Pavement Evaluation General Summary. Specific recommendations for maintenance are identified in Table 3-2.

The ISR is an information system designed to help the Army monitor some of the basic elements that affect the quality of life on installations. The ISR also supports decision-making by giving managers an objective means and a common methodology for comparing conditions across installations and across functional areas.

Recommendations for structural improvements have been defined in terms of overlays in this report. In some instances, overlays may not be the most cost effective or best engineering alternative for pavement strengthening. It should be noted that the overlay requirements shown in Table 3-2 were determined based on representative conditions at the time of testing and should be considered minimum values until verified by further investigation. These overlays should be used as a guide when programming funds for design projects. Reconstruction is recommended for all features with Very poor or lower PCI ratings and/or large

overlay requirements. Prior to advertising an improvement project, a thorough pavement analysis and design should be completed to select the most cost-effective improvement technique. All designs should be reviewed by the U.S. Army Corps of Engineers Transportation Systems Center to ensure that they are in accordance with current design criteria.

Recommended overlay thicknesses follow the criteria for minimum thicknesses contained in UFC 3-260-02 (Headquarters, Departments of the Army, Navy, and the Air Force 2001b). Where calculated thicknesses are greater than the required minimum thickness, the values were rounded up to the next higher 13 mm (1/2-in.).

Maintenance and repair (M&R) recommendations are based on the changes needed to provide the minimum required PCI. AR 420-72 (Headquarters, Department of the Army 2000) states that installation airfield pavements shall be maintained to at least the following PCI:

All runways > 70  
Primary taxiways < 60  
Aprons and secondary taxiways > 55

## Recommendations

Steps 1 through 5 of the flow chart shown in Figure 3-1 were used in determining the recommendations suggested in Table 3-2. The M&R alternatives suggested for the existing surfaces were selected from those listed for various distresses in flexible pavements shown in Table 3-3 and rigid pavements shown in Table 3-4. In many instances, the performance of a specific alternative depends upon the geographical location and expertise of local contractors. Therefore, it is suggested that the local DPW personnel review all recommendations. Local costs for the approved alternatives can then be used with the Micro PAVER program to obtain a reasonable cost estimate. All overlay, repair, or major repair should be in accordance with UFC 3-269-02 (Headquarters, Departments of the Army, Navy, and the Air Force 2001b) that specifies that the following pavements be rigid pavement: all paved areas on which aircraft or helicopters are regularly parked, maintained, serviced, or preflight checked, on hangar floors and access aprons; on runway ends (305 m (1,000 ft) of a Class B runway; primary taxiways for Class B runways; hazardous cargo, power check, compass calibration, warmup, alert, arm/disarm, holding, and washrack pads; and any other area where it can be documented that a flexible pavement will be damaged by jet blast or by spillage of fuel or hydraulic fluid.

The PCI was developed to determine maintenance and repair needs. If the PCI is low, maintenance or repair is needed to increase the PCI. If the PCI is low and the PCN is greater than the ACN, localized maintenance or repair will generally be an acceptable solution. Although these maintenance activities and repairs will improve the PCI to acceptable levels, they may not be the most cost-effective alternative. An overlay or other overall improvement may be more

cost-effective than considerable localized maintenance or repairs. Certainly, if the current PCI is less than 25, overall improvements should be investigated. When an overlay is recommended, the maintenance recommended is that which is needed to keep the pavement serviceable and safe and its PCI at the required minimum until the overlay is applied. The PCN is used to specify the structural capability of an airfield pavement. If the design aircraft's ACN is larger than the computed PCN, the pavement is structurally inadequate to support the mission traffic. If only repairs to improve the PCI are applied, the pavement could deteriorate quite rapidly. Structural improvements are required to increase the load-carrying capacity so that the PCN is greater than or equal to the ACN (aircraft load). Even if the PCI is high, structural improvements are necessary to support the mission traffic if the PCN is less than the design ACN.

The PCIs of five runway features (R2A through R6A), five taxiway features (T1A, T3A through T6A), and one apron feature (A2B) fail to meet the minimum acceptable level outlined above. Due to the severity and quantity of surface distresses observed on the remaining ten features, maintenance or repair is not recommended. To meet the minimum PCI requirements resealing the joints, replacing the faulted slabs, and patching the medium- and high-severity spalls is recommended for T3A. The estimated cost is about \$33,500. Although the PCI of ten features (A4B through A13B) meet the minimum PCI requirements, approximately \$400,000 (FY 03) in M & R is recommended. M & R for these features include resealing the PCC joints, patching all medium- and high-severity spalls, and replacing all medium- and high-severity shattered, faulted, and "D" cracked slabs. An airfield pavements cost estimating guide for various maintenance and repair alternatives is shown in Table 3-4.




Figure 3-1. Flowchart for determination of maintenance and repair recommendations

**Table 3-1**  
**Airfield Pavement Evaluation General Summary**

Pavement Feature	PCI	ACN/PCN <sup>2</sup>	ISR Rating <sup>3</sup>	Work Classification <sup>1</sup>			
				Do Nothing	Maintenance	Repair	Major Repair
R1A	92	2.73	Red				X
R2A	25	1.56	Red				X
R3A	14	2.00	Red				X
R4A	22	1.56	Red				X
R5A	26	1.56	Red				X
R6A	33	1.56	Red				X
R7A	93	1.15	Amber			X	
T1A	2	12.0	Red				X
T2A	90	1.11	Amber			X	
T3A	50	1.03	Red			X	
T4B	19	2.25	Red				X
T5A	5	2.25	Red				X
T6A	5	3.50	Red				X
A1B	92	1.07	Amber			X	
A2B	5	18.00	Red				X
A3B	93	2.55	Red			X	
A4B	82	1.50	Amber			X	
A5B	84	1.65	Red			X	
A6B	78	1.67	Red			X	
A7B	80	1.00	Green		X		
A8B	80	1.00	Green		X		
A9B	64	0.65	Amber		X		
A10B	84	1.00	Green		X		
A11B	85	1.10	Amber			X	
A12B	84	1.10	Amber			X	
A13B	81	1.00	Green		X		

<sup>1</sup> Work is categorized for preliminary planning purposes only. Classification of work for administrative approval is an installation responsibility. Policy guidance for airfield pavements is provided in AR 420-72. *Maintenance* is usually performed on paved areas with a PCI greater than the minimum required and encompasses primarily the day-to-day routine work. Maintenance includes items such as sealing cracks and joints, repairing potholes, patching, repairing spalls, and applying rejuvenators. *Repair* is the restoration of a failed or rapidly deteriorating section of pavement to a good or excellent condition to such that it may be utilized for its designated purpose. Repair is usually applied to pavements with a PCI less than the minimum required. Examples are: recycling, overlays, slab replacement, and repairing drainage structures. *Major repair (construction)* relates to the alteration, extension, replacement, or upgrading of an existing facility. Major repair examples include: widening or lengthening a surfaced area, strengthening a pavement to support a new mission, and replacement of an entire facility.

<sup>2</sup> Determined for design aircraft.

<sup>3</sup> Based on the PCI and ACN/PCN ratio of the pavement feature.



**Table 3-2**

**Summary of Overlay and Maintenance Requirements for the Day-to-Day Traffic Operations**

Feature	Area Sq m (sq yd)	Overlay Requirements, mm (in.) <sup>1</sup>			Maintenance and Repair Alternatives for Existing Surfaces
		AC	PCC Partial Bond	PCC with no Bond	
Runway 13-31					
R1A <sup>2</sup>	3484 (4,167)	140 (5.5)	NA	See <sup>3</sup>	The PCI of this feature is above that required for runways. However, it is structurally inadequate to support the design traffic. Overlaying with AC is not recommended. PCC reconstruction should be considered if this feature is to withstand the projected traffic.
R2A <sup>2</sup>	3484 (4,167)	51 (2.0)	NA	See <sup>3</sup>	The PCI of this feature is far below that required for runways and the existing pavement is structurally inadequate to support the design traffic. Crack sealing, surface sealing, patching, and/or overlaying are not recommended. PCC reconstruction should be considered if this feature is to withstand the projected traffic.
R3A	3484 (4,167)	51 (2.0)	NA	See <sup>3</sup>	Same as for R2A.
R4A	17 837 (21,333)	51 (2.0)	NA	See <sup>3</sup>	The PCI of this feature is far below that required for runways and the existing pavement is structurally inadequate to support the design traffic. Crack sealing, surface sealing, patching, and/or overlaying are not recommended. Reconstruction should be considered if this feature is to withstand the projected traffic.
R5A <sup>2</sup>	3484 (4,167)	51 (2.0)	NA	See <sup>3</sup>	Same as for R2A.
R6A <sup>2</sup>	2787 (3,333)	51 (2.0)	NA	See <sup>3</sup>	Same as for R2A.
R7A <sup>2</sup>	1359 (1,625)	NA	152 (6.0)	165 (6.5)	The PCI of this feature is above that required for runways. However, it is structurally inadequate to support the design traffic. PCC reconstruction should be considered if this feature is to withstand the projected traffic.
Taxiway B					
T1A	4877 (5,833)	-- <sup>4</sup>	-- <sup>4</sup>	-- <sup>4</sup>	The PCI of this feature is far below that required for taxiways and the existing pavement is structurally inadequate to support the design traffic. The PCI rating of T1A is failed. Therefore, M & R is not recommended. Reconstruction is required if this feature is to withstand the projected traffic.
Taxiway C					
T2A <sup>2</sup>	1858 (2,222)	NA	152 (6.0)	152 (6.0)	The PCI of this feature is above that required for taxiways. However, structural improvements are required in order for the pavement to withstand the design traffic.
T6A <sup>2</sup>	881 (1,053)	140 (5.5)	NA	See <sup>3</sup>	Same as for T1A.
Taxiway D					
T3A <sup>2</sup>	2750 (3,289)	NA	152 (6.0)	152 (6.0)	Increase the PCI to an acceptable level by cleaning and sealing the joints with a high-quality sealer, <sup>5</sup> replacing the faulted slabs, and patching the medium- and high-severity spalls with an epoxy concrete patch or a full-depth patch. Structural improvements are required to withstand the design traffic.
(Sheet 1 of 3)					
<sup>1</sup> For planning purposes only.					
<sup>2</sup> UFC 3-260-02 (Headquarters, Departments of the Army, Navy, and the Air Force 2001b) requires that the pavement be a rigid pavement.					
<sup>3</sup> Was not calculated because feature was evaluated as a flexible pavement.					
<sup>4</sup> Reconstruction is recommended because the ISM is less than the lower limit of LOW.					
<sup>5</sup> See TM 5-882-11/AFP 88-6, Chapter 7 (Headquarters, Departments of the Army and Air Force 1993) for guidance.					

<sup>1</sup> For planning purposes only.

<sup>2</sup> UFC 3-260-02 (Headquarters, Departments of the Army, Navy, and the Air Force 2001b) requires that the pavement be a rigid pavement.

<sup>3</sup> Was not calculated because feature was evaluated as a flexible pavement.

<sup>4</sup> Reconstruction is recommended because the ISM is less than the lower limit of LOW.

<sup>5</sup> See TM 5-882-11/AFP 88-6, Chapter 7 (Headquarters, Departments of the Army and Air Force 1993) for guidance.

Table 3-2 (Continued)				
Feature	Area Sq m (sq yd)	Overlay Requirements, mm (in.) <sup>1</sup>		
		AC	PCC Partial Bond	PCC with no Bond
Maintenance and Repair Alternatives for Existing Surfaces				
Compass Rose Taxiway				
T4B	780 (933)	51 (2.0)	NA	See <sup>3</sup>
The PCI of this feature is below that required for taxiways and the existing pavement is structurally inadequate to support the projected traffic. Due to the very poor surface condition and structural condition, M & R is not recommended. Reconstruction should be considered.				
Alpha Lane				
T5A	18 812 (22,500)	51 (2.0)	NA	See <sup>3</sup>
The PCI of this feature is far below that required for hoverlanes and the existing pavement is structurally inadequate to support the design traffic. The PCI rating of T5A is failed. Due to the surface condition and structural condition, M & R is not recommended. Reconstruction should be considered.				
13 Warm-up				
A1B <sup>2</sup>	3902 (4,667)	NA	152 (6.0)	152 (6.0)
The PCI of this feature is above that required for aprons. Structural improvements are required. A PCC overlay or PCC reconstruction should be considered if this feature is to withstand the projected traffic.				
31 Warm-up				
A2B <sup>2</sup>	4854 (5,806)	254 (10.0)	NA	See <sup>3</sup>
The PCI of this feature is far below that required for warm-up areas and the existing pavement is structurally inadequate to support the design traffic. The PCI rating of A2B is failed. Due to the surface condition and structural condition, M & R is not recommended. Reconstruction should be considered.				
Hoverlane				
A3B <sup>2</sup>	22 993 (27,500)	76 (3.0)	NA	See <sup>3</sup>
The PCI of this feature is above that required for hoverlanes. Structural improvements are required to withstand the projected traffic. If this feature is required to sustain C-130 traffic, reconstruction with PCC should be considered.				
Transient Parking Ramp				
A4B <sup>2</sup>	4139 (4,950)	NA	152 (6.0)	191 (7.5)
The PCI of this feature is above that required for parking areas. However, it is recommended that joints be cleaned and sealed with a high quality-quality sealant. <sup>5</sup> PCC reconstruction is recommended if this feature is to withstand the projected traffic.				
Charlie Parking Ramp				
A5B <sup>2</sup>	12 646 (15,125)	NA	165 (6.5)	203 (8.0)
Same as for A4B.				
A6B <sup>2</sup>	19 161 (22,917)	NA	178 (7.0)	216 (8.5)
The PCI of this feature is above that required for parking areas. However, it is recommended that joints be cleaned and sealed with a high quality-quality sealant. <sup>5</sup> the high- and medium-severity spalls be repaired with an epoxy concrete patch or a full-depth patch, the slabs with high- and medium-severity "D" cracking and/or large patches be replaced. PCC reconstruction is recommended if this feature is to withstand the projected traffic.				
(Sheet 2 of 3)				
<sup>1</sup> For planning purposes only.				
<sup>2</sup> UFC 3-260-02 (Headquarters, Departments of the Army, Navy, and the Air Force 2001b) requires that the pavement be a rigid pavement..				
<sup>3</sup> Was not calculated because feature was evaluated as a flexible pavement.				
<sup>4</sup> Reconstruction is recommended because the ISM is less than the lower limit of LOW.				
<sup>5</sup> See TM 5-882-11/AFP 88-6, Chapter 7 (Headquarters, Departments of the Army and Air Force 1993) for guidance.				

Table 3-2 (Concluded)				
Feature	Area Sq m (sq yd)	Overlay Requirements, mm (in.) <sup>1</sup>		
		AC	PCC Partial Bond	PCC with no Bond
Maintenance and Repair Alternatives for Existing Surfaces				
Delta Parking Ramp				
A7B <sup>2</sup>	4674 (5,590)	NA	0 (0.0)	0 (0.0)
The PCI of this feature is above that required for aircraft parking areas. However, it is recommended that joints be cleaned and sealed with a high-quality sealant <sup>5</sup> and all high-severity "D" cracked slabs be replaced.				
A8B <sup>2</sup>	5661 (6,771)	NA	0 (0.0)	0 (0.0)
The PCI of this feature is above that required for aircraft parking areas. However, it is recommended that the joints be cleaned and then sealed with a high-quality sealant. <sup>5</sup>				
A9B <sup>2</sup>	26 909 (32,184)	NA	0 (0.0)	0 (0.0)
The PCI of this feature is above that required for parking areas. However, it is recommended that joints be cleaned and sealed with a high quality-quality sealant, <sup>5</sup> the high- and medium-severity spalls be repaired with an epoxy concrete patch or a full-depth patch, the slabs with high-severity "D" cracking and faulted slabs be replaced.				
B East Parking Ramp				
A10B <sup>2</sup>	4982 5,958)	NA	0 (0.0)	0 (0.0)
The PCI of this feature is above that required for parking areas. However, it is recommended that joints be cleaned and sealed with a high quality-quality sealant <sup>5</sup> and that the high- and medium-severity faulted slabs be replaced.				
B West Parking Ramp				
A11B <sup>2</sup>	4982 5,958)	NA	152 (6.0)	152 (6.0)
The PCI of this feature is above that required for parking areas. However, it is recommended that joints be cleaned and sealed with a high quality-quality sealant <sup>5</sup> and that the shattered slabs be replaced. Structural improvements are required to withstand the projected traffic.				
Compass Rose				
A12B <sup>2</sup>	929 (1,111)	NA	152 (6.0)	165 (6.5)
The PCI of this feature is above that required for compass calibration areas. However, it is recommended that joints be cleaned and sealed with a high quality-quality sealant. <sup>5</sup> Structural improvements are required to withstand the projected traffic.				
Alpha Ramp				
A13B <sup>2</sup>	59 990 (71,850)	NA	0 (0.0)	0 (0.0)
The PCI of this feature is above that required for parking areas. However, it is recommended that the high- and medium-severity spalls be repaired with an epoxy concrete patch or a full-depth patch and that the faulted slabs be replaced.				
(Sheet 3 of 3)				
<sup>1</sup> For planning purposes only.				
<sup>2</sup> UFC 3-260-02 (Headquarters, Departments of the Army, Navy, and the Air Force 2001b) requires that the pavement be a rigid pavement.				
<sup>3</sup> Was not calculated because feature was evaluated as a flexible pavement.				
<sup>4</sup> Reconstruction is recommended because the ISM is less than the lower limit of LOW.				
<sup>5</sup> See TM 5-882-11/AFP 88-6, Chapter 7 (Headquarters, Departments of the Army and Air Force 1993) for guidance.				

Table 3-3 Maintenance, Repair, and Major Repair Alternatives for Airfield Pavements, Flexible																			
Distress Type	Maintenance					Repair										Major Repair			
	Seal Minor Cracks	Repair Pot- Holes	Partial- Depth Patching	Apply Rejuve- nators <sup>1</sup>	Seal Major Cracks	Full- Depth Patching	Micro- Surfacing	Slurry Seal <sup>2</sup>	Thin AC Overlays <sup>3</sup>	Surface Milling	Grooving	Porous Friction Course	Repair Drainage Facilities <sup>4</sup>	Surface Recycling	AC Structural Overlay <sup>3</sup>	PCC Structural Overlay	Remove Existing Surface and Reconstruct	Hot Recycle	Cold Recycle
Alligator cracking	L	M,H	M			M,H	L	L					L,M,H		M,H	M,H	H		
Bleeding										A				A			A	A	
Block cracking	L,M			L	M,H		L,M	L						M	M,H			M,H	M,H
Corrugation			L,M			L,M,H	L,M		M,H	L,M							M,H		
Depression			L,M,H			M,H	L		M,H				L,M,H				H		
Jet blast				A		A	A		A										
Reflection cracking	L,M				M,H		L,M	L							M,H			H	
Longitudinal and transverse cracking	L,M				M,H		L,M	L							M,H			H	
Oil spillage			A			A			A	A				A			A	A	
Patching	L,M		M		M	M,H									M,H		H	H	
Polished aggregate							A	A	A	A	A	A		A					
Raveling/weathering		M,H		L,M		M	L,M	L	M,H	M				M,H		H	H	M,H	
Rutting			L,M			L,M,H	L						L,M,H		M,H	H	H	M,H	
Shoving			L			L,M				L,M							M,H	M,H	
Slippage cracking	A		A		A	A									A		A	A	
Swell			L,M			M,H				L,M			L,M,H				H		

Note: L = low severity level; M = medium severity level; H = high severity level; A = no severity levels for this distress.

<sup>1</sup> Not to be used on high speed areas due to increased skid potential.

<sup>2</sup> Not to be used on heavy traffic areas.

<sup>3</sup> Patch distressed areas prior to overlay.

<sup>4</sup> Drainage facilities to be repaired as needed.

Table 3-4 Maintenance, Repair, and Major Repair Alternatives for Airfield Pavements, Rigid																	
Distress Type	Maintenance							Repair							Major Repair		
	Seal Minor Cracks	Joint Seal	Partial Patch	Epoxy Patch	Seal Major Cracks	Full-Depth Patch	Under Sealing	Slab Grinding	Surface Milling	AC Overlay	PCC Overlay	Slab Replacement	Crack & Seal with AC Structural Overlay	AC Overlay w/ Geotextile	Repair/Install Surface/Subsurface Drainage System <sup>1</sup>	PCC Recycling	Remove Existing PCC and Reconstruct
Blowup			L,M			M,H						H					
Corner break	L			M,H	M,H	M,H						H					
Longitudinal/Transverse/ Diagonal cracking	L,M				M,H					H	H	H	M,H	H	L,M,H	H	H
D cracking	L		M,H		M,H	H						H				H	H
Joint seal damage		M,H															
Patching (small) <5 ft²	L,M		M	L,M	M,H	M,H						H					
Patching/utility cut	L,M		M	L,M	M,H	M,H						H					H
Popouts <sup>2</sup>				A						A	A						
Pumping	A	A			A		A								A		
Scaling/map cracking			M,H					M,H		M,H	M,H						
Fault/settlement		L,M					M,H	L,M	M,H						L,M,H		
Shattered slab	L				L,M					M,H	M,H	M,H		H	L,M,H	H	H
Shrinkage crack <sup>3</sup>																	
Spalling (joints)		L	L,M	L,M,H	M,H	M,H											
Spalling (corner)			L,M	L,M	M,H	M,H											

Note: L = low severity level; M = medium severity level; H = high severity level; A = no severity levels for this distress.

<sup>1</sup> Drainage facilities to be repaired as needed.

<sup>2</sup> Popouts normally do not require maintenance.

<sup>3</sup> Shrinkage cracks normally do not require maintenance.

Note: L = low severity level; M = medium severity level; H = high severity level; A = no severity levels for this distress.

<sup>1</sup> Drainage facilities to be repaired as needed.

<sup>2</sup> Popouts normally do not require maintenance.

<sup>3</sup> Shrinkage cracks normally do not require maintenance.

**Table 3-5  
Airfield Pavements M&R Cost Estimating Guide**

Item	Description	U/M	Unit Cost (\$)					
			FY02	FY03	FY04	FY05	FY06	FY07
1	Remove/replace 10" PCC w/14" PCC including 6" base	SY	74.92	76.80	78.71	80.68	82.70	84.76
2	PCC Construction	SY-IN	3.87	3.92	4.02	4.12	4.22	4.33
3	Remove/replace 6" Bituminous Pavement w/14" PCC including 6" base	SY	68.69	70.41	72.17	73.97	75.82	77.71
4	Asphalt Concrete Overlay							
	-- Airfield Mix	TONS	52.89	54.21	55.57	56.95	58.37	59.83
		SY-IN	2.87	2.94	3.01	3.09	3.17	3.25
	-- Highway Mix	TONS	48.71	49.92	51.17	52.45	53.76	55.10
		SY-IN	2.65	2.71	2.78	2.85	2.92	2.99
5	Joint Resealing (JFR)	LF	2.25	2.30	2.36	2.42	2.48	2.54
6	Joint Resealing (NON - JFR)	LF	2.00	2.05	2.10	2.15	2.20	2.26
7	Crack Routing/Sealing (PCC)	LF	2.76	2.83	2.90	2.97	3.04	3.12
8	Neoprene Compression Joint Seal							
	-- Saw Cutting Only	LF	1.40	1.43	1.47	1.50	1.54	1.56
	-- Lubrication, Furnish and Install Compression Seal							
	-- 1/2-in. wide joint	LF	3.47	3.55	3.64	3.73	3.82	3.92
	-- 5/8-in. wide joint	LF	3.85	3.94	4.04	4.14	4.24	4.35
	-- 3/4-in. wide joint	LF	4.72	4.84	4.96	5.09	5.22	5.35
9	Spall Repairs (Epoxy-Bonded PCC)	SF	26.58	27.25	27.93	28.63	29.35	30.08
10	PCC Pavement Removal (To Base Course) T < 12"	SY-IN	1.06	1.09	1.12	1.15	1.18	1.21
11	PCC Pavement Removal (To Base Course) T ≥ 12"	SY-IN	1.50	1.53	1.57	1.61	1.65	1.69
12	Asphalt Pavement Removal (to base course)	SY-IN	0.97	0.99	1.01	1.04	1.07	1.09
13	Base/Subgrade Removal	SY-IN	0.64	0.66	0.66	0.69	0.71	0.72
14	Asphalt Milling/Profiling/Grinding (Cold)							
	-- up to 1-in. depth	SY	1.64	1.68	1.72	1.77	1.81	1.86
	-- up to 2-in. depth	SY	2.37	2.43	2.49	2.55	2.61	2.68
	-- up to 3-in. depth	SY	2.50	2.56	2.62	2.69	2.76	2.83
	-- up to 4-in. depth	SY	2.63	2.69	2.76	2.83	2.90	2.97
	-- small difficult jobs (hard agg. etc.)	SY-IN	3.12	3.20	3.28	3.36	3.44	3.53
15	PC Concrete Grinding/Profiling (Normally 1/2 in. is max Feasible)	SY-IN	19.98	20.48	20.99	21.52	22.06	22.61
16	Heater-Scarification (3/4--") - rejuvenation	SY	1.39	1.42	1.46	1.49	1.53	1.57
17	Cold Recycling 6" AC with 4-in.-thick AC O/L	SY	18.34	18.80	19.27	19.75	20.24	20.75
18	Slurry Seal	SY	1.65	1.69	1.73	1.78	1.82	1.87

**(Continued)**

Table 3-5 (Concluded)								
Item	Description	U/M	Unit Cost (\$)					
			FY02	FY03	FY04	FY05	FY06	FY07
19	Micro-Surfacing	SY	2.37	2.43	2.49	2.55	2.61	2.68
20	Single Bituminous Surface Treatment	SY	2.00	2.05	2.10	2.15	2.20	2.26
21	Double Bituminous Surface Treatment	SY	2.89	2.96	3.03	3.11	3.19	3.27
22	Rubberized Coal Tar Pitch Emulsion Sand Slurry Surface Treatment	SY	1.81	1.85	1.90	1.94	1.99	2.04
23	Rubberized Coal Tar Pitch Emulsion (No Aggregate)	SY	1.19	1.22	1.25	1.28	1.31	1.34
24	Fog Seal	SY	0.81	0.83	0.85	0.87	0.89	0.91
25	Rubberized Asphalt Systems							
	-- Stress Absorbing Membrane (SAM) Interlayer	SY	4.62	4.74	4.86	4.98	5.10	5.23
	-- SAM Seal Coat (uncoated chips)	SY	4.87	5.00	5.13	5.25	5.38	5.52
	-- SAM Seal Coat (precoated chips)	SY	5.24	5.37	5.50	5.64	5.78	5.93
26	Reinforcing Fabric Membranes (including tack coat)	SY	2.60	2.66	2.73	2.79	2.86	2.93
27	Elastomeric Inlay installed in Existing PCC, Complete (2' Wide X 100' Long X 2" Deep)	EA	26.3K	26.9K	27.6K	28.3K	29.0K	29.7K
28	PC Concrete Inlay (20' X 120' X 12" in Asphalt Pavement)	EA	18.7K	19.2K	19.7K	20.2K	20.7K	21.2K
29	Runway Grooving							
	-- Asphalt Concrete Pavement	SY	2.00	2.05	2.10	2.15	2.20	2.26
	-- Portland Concrete Pavement	SY	4.37	4.48	4.59	4.71	4.83	4.95
30	Runway Rubber Removal (High Pressure Water Blasting Method)	SF	0.062	0.063	0.065	0.066	0.067	0.069
31	Paint Removal							
	-- Partial Removal (Remove only loose, flaking, or poorly bonded paint)	SF	0.062	0.063	0.065	0.066	0.067	0.069
	-- Complete Removal (Using High Pressure water with sand injection)	SF	0.72	0.74	0.76	0.78	0.80	0.82
32	Airfield Marking							
	-- Reflectorized	SF	0.48	0.50	0.51	0.53	0.54	0.56
	-- Non-Reflectorized	SF	0.27	0.28	0.29	0.29	0.30	0.30
33	Street Marking							
	-- Reflectorized	SF	0.35	0.36	0.37	0.38	0.39	0.40
	-- Non-Reflectorized	SF	0.22	0.23	0.24	0.24	0.25	0.25
34	Random Slab Replacement							
	-- 12' by 12' by 12-in. thick	EA	1.3K	1.3K	1.3K	1.4K	1.4K	1.5K
	-- 25' by 25' by 12-in. thick	EA	5.0K	5.2K	5.3K	5.5K	5.6K	5.8K
	-- 25' by 25' by 18-in. thick	EA	7.5K	7.6K	7.8K	8.0K	8.2K	8.4K
	-- 25' by 25' slab	SY-IN	5.84	5.99	6.14	6.29	6.45	6.61
35	Soil Cement Stabilization (10 percent by weight)	SY-IN	0.53	0.54	0.55	0.57	0.58	0.60

## 4 Conclusions

---

The maintenance and rehabilitation alternatives discussed in Chapter 3 and summarized in Table 3-2 should be performed as soon as possible to retain the full benefit of the structural capacity of the existing pavements. The M & R alternatives suggested for the existing surfaces were selected from the alternatives listed for the various distresses shown in Tables 3-3 and 3-4. In many instances the performance of a specific alternative is dependent upon local conditions and contractors.

The operational ACN for the airfield rigid pavement facilities is 30/R/B/W/T and for the flexible pavement facilities 30/F/C/W/T. PCNs for each facility are shown in Illustration 1. ISR ratings based on the ACN/PCN ratios and the PCIs of each respective facility are shown in Illustration 2.

PCN's for the controlling feature of each pavement facility during the thaw-weakened periods are provided in Table D4 as guidance to the airfield operator for managing airfield operations during the November through March time frame.



# References

---

- American Society of Testing and Materials. (1994). "Standard test method for airport pavement condition index surveys," Designation: D 5340-93, West Conshohocken, PA.
- American Society of Testing and Materials. (1999). "Standard practice for use of metric (SI) units in building design and construction," Designation: E 621-94, West Conshohocken, PA.
- Bush, Albert J. III. (1986). "Performance prediction of low volume airfield pavements," Technical Report GL-86-14, U.S. Army Engineer Waterways Experiment Station, Vicksburg, MS.
- Headquarters, Department of the Army. (1990). "Air traffic control, airspace, airfields, flight activities, and navigational aids," Army Regulation 95-2, Washington, DC.
- \_\_\_\_\_. (2000). "Transportation infrastructure and dams," Army Regulation 420-72, Washington, DC.
- Headquarters, U.S. Army Corps of Engineers. (1991). "Engineering and design aircraft characteristics for airfield-heliport design and evaluation," Engineering Technical Letter ETL 1110-3-394, U.S. Army Corps of Engineers, Washington, DC.
- Headquarters, Departments of the Army and the Air Force. (1993). "Standard practice for sealing joints and cracks in rigid and flexible pavements," Technical Manual TM 5-822-11/AFP 88-6, Chap. 7, Washington, DC.
- Headquarters, Departments of the Army, Navy, and the Air Force. (1978). "Flexible pavement design for airfields," Technical Manual TM 5-825-2/DM 21.3/ AFM 88-6, Chap. 2, Washington, DC.
- \_\_\_\_\_. (2001a). "Airfield pavement evaluation," Unified Facilities Criteria, UFC 3-260-03, Washington, DC.
- \_\_\_\_\_. (2001b). "Pavement design for airfields," Unified Facilities Criteria, UFC 3-260-02, Washington, DC.

# Appendix A

## Background Data

---

### Description of the Airfield

Butts Army Airfield (BAAF) is located at Fort Carson, Colorado, in El Paso County and is approximately 11.3 km (7 miles) south of Colorado Springs, CO. The airfield is located on a gently rolling prairie with sharply rising mountains 9.7 km (6 miles) to 16.1 km (10 miles) west of the airfield. The elevation of the airfield is 1,789 m (5,871 ft) above mean sea level. The soils in the area consist of sand and gravel deposits with some Aeolian deposits consisting of clayey sandy silt. The principal soil types of the airfield site are classified as sandy clays and sands.

A layout of the airfield is shown in Figure A1. Pavement feature identifications and locations are shown in Figure A2. In May 2002 the airfield consisted of one active runway (13-31), an old runway now used as a hoverlane (Alpha Lane), various parking aprons, connecting taxiways, warm-up areas, and a compass rose. Runway 13-31 was 1402 m (4,600 ft) long and 23 m (75 ft) wide. The Alpha Lane is 23 m (75 ft) wide and 823 m (2700 ft) long.

The climatological data used herein were obtained from the weather station at Fort Carson, CO. The annual rainfall in the area is about 335 mm (13.2 in.) and the annual snowfall is 719 mm (28.3 in.). The maximum and minimum temperatures were 38°C and -29°C (100°F and -20°F), respectively. Temperature and precipitation data are summarized in Table A1.

### Previous Reports

Pertinent data for use in this evaluation were extracted from the previous reports listed below:

- a. U.S. Army Engineer Waterways Experiment Station, "Airfield Pavement Evaluation, Butts Army Airfield, Fort Carson, Colorado," Miscellaneous Paper GL-96-19, August 1996, Vicksburg, MS.

- b. U.S. Army Engineer Waterways Experiment Station, "Airfield Pavement Evaluation, Butts Army Airfield, Fort Carson, Colorado," Miscellaneous Paper GL-94-35, August 1994, Vicksburg, MS.
- c. U.S. Army Engineer Waterways Experiment Station, "Condition Survey, Butts Army Airfield, Fort Carson, Colorado," Miscellaneous Paper GL 89-23, September 1989, Vicksburg, MS.
- d. U.S. Army Engineer Waterways Experiment Station, "Airfield Pavement Evaluation, Butts Army Airfield, Fort Carson, Colorado," Miscellaneous Paper S-85-17, August 1985, Vicksburg, MS.
- e. U.S. Army Engineer Waterways Experiment Station, "Airfield Pavement Evaluation, Butts Army Airfield, Fort Carson, Colorado," Miscellaneous Paper S-76-22, November 1976, Vicksburg, MS.
- f. U.S. Army Engineer Waterways Experiment Station, "Condition Survey, Butts Army Airfield, Fort Carson, Colorado," Miscellaneous Paper S-72-26, June 1972, Vicksburg, MS.
- g. U.S. Army Engineer Division Ohio River, "Pavement Evaluation, Butts Army Airfield, Fort Carson, Colorado," October 1960, Cincinnati, OH.
- h. U.S. Army Engineer Waterways Experiment Station, "Army Airfield Pavement Evaluation, Butts Army Airfield, Fort Carson, Colorado," Technical Report No.3-466, July 1960, Vicksburg, MS.

## Design and Construction History

The original pavements at BAAF were constructed in 1954 and consisted of a steel-plank landing mat runway and hardstands that have since been removed. Upgrading the pavement, including new construction and repair of the existing facilities, was performed at various periods from 1958 through 2001. The overrun for Runway 13-31 and the Taxiway Bravo were constructed in 1960. Alpha Lane, the Warm-Up Ramps, the Compass Rose and taxiway, the Hover Lane, and the 178 mm (7 in.) thick Portland cement concrete portion of the Charlie Parking Ramp were constructed in 1964. Taxiway Delta, the 229 mm (9 in.) thick portion of the Delta Parking Ramp, and both Bravo East and West Rotary-wing Parking Ramps were constructed in 1981. The Alpha Ramp was constructed in 1991. In 2001, the Hoverlane was reconstructed with 4 in. of base and 4 in. of AC for a total of 8 in. The same year the North Overrun was reconstructed with the same 4/4, and an 8-in.-thick, 43-m- (143-ft-) long PCC addition was constructed on the South end of the runway. This PCC addition was to be used for a C-130 turnaround area. Table A2 presents the history of the major construction activities at BAAF. A summary of the physical property data of the various pavement features is shown in Table A3.

## Traffic History

The fixed-wing facilities (Runway 13-31, Charlie taxiway and ramp, Transient Ramp, Delta taxiway, and 13 Warm-up Ramp) were evaluated for 6,000 passes of a 70 300 kg (155,000 lb) C-130 aircraft. Traffic logs for the past three years indicate approximately 300 annual landings of a C-130. All other features were evaluated for 50,000 passes of a 22 700 kg (50,000 lb) CH-47 rotary-wing aircraft.





Figure A1. Layout of airfield and facility identifications



**Table A1**  
**Climatological Data Summary**

	J	F	M	A	M	J	J	A	S	O	N	D	ANN	YRS REC
Temperature, °C (°F)														
Highest	23 (73)	23 (73)	26 (79)	31 (87)	33 (92)	38 (100)	37 (99)	38 (100)	34 (93)	31 (87)	26 (78)	23 (73)	38 (100)	22
Mean Daily Max	6 (43)	8 (47)	12 (54)	16 (62)	21 (70)	27 (80)	30 (86)	28 (83)	25 (77)	19 (67)	12 (53)	7 (45)	18 (64)	22
Mean	0 (32)	2 (35)	6 (42)	10 (50)	14 (58)	21 (69)	23 (74)	22 (72)	18 (64)	12 (54)	5 (41)	2 (35)	12 (53)	22
Mean Daily Min	-6 (22)	-4 (24)	-1 (31)	3 (37)	8 (46)	13 (55)	16 (60)	15 (59)	11 (52)	6 (42)	-1 (31)	-4 (25)	5 (41)	22
Lowest	-23 (-10)	-25 (-13)	-17 (2)	-15 (5)	-5 (23)	2 (36)	8 (47)	3 (38)	-3 (27)	-14 (7)	-19 (-3)	-29 (-20)	-29 (-20)	22
Precipitation, mm (in.)														
Mean	5 (0.2)	10 (0.4)	23 (0.9)	33 (1.3)	33 (1.3)	48 (1.9)	79 (3.1)	58 (2.3)	33 (1.3)	20 (0.8)	15 (0.6)	5 (0.2)	335 (13.2)	22
Snowfall, mm (in.)														
Mean	107 (4.2)	125 (4.9)	193 (7.6)	102 (4.0)	5 (0.2)	0	0	0	20 (0.8)	38 (1.5)	119 (4.7)	71 (2.8)	719 (28.3)	22
Relative Humidity, %														
Mean 0400 LST 1400 LST	66 42	64 39	66 36	69 33	72 36	66 32	69 31	68 34	66 32	58 30	63 36	59 39	66 35	22
Source of data: <a href="http://www.afccc.af.mil/climo">www.afccc.af.mil/climo</a> Fort Carson, Colorado														

**Table A2  
Construction History**

Pavement Facility (Feature)	Surface Pavement		Construction Date
	Thickness, mm (in.)	Type	
Runway 13-31 R2A, R6A R3A, R4A, R5A R2A, R3A, R4A, R5A, R6A R2A, R3A, R4A, R5A, R6A R2A, R3A, R4A, R5A, R6A R2A, R3A, R4A, R5A, R6A R7A	686 (27.0) <sup>1</sup> 533 (21.0) <sup>1</sup> 25 (1.0) <sup>2</sup> 38 (1.5) <sup>2</sup> 25 (1.0) <sup>2</sup> 51 (2.0) <sup>2</sup> 203 (8.0) <sup>4</sup>	AC AC AC AC AC AC PCC	1959 1959 1965 1969 1973 1986 2001
Runway 13-31 Overrun R1A R1A R1A	254 (10.0) <sup>1</sup> 25 (1.0) <sup>2</sup> 102 (4.0) <sup>4</sup>	BST <sup>3</sup> AC AC	1960 1973 2001
Alpha Lane T5A T5A	406 (16.0) <sup>1</sup> 25 (1.0) <sup>2</sup>	AC AC	1964 1973
Taxiway B T1A T1A	254 (10.0) <sup>1</sup> 25 (1.0) <sup>2</sup>	BST AC	1960 1973
Taxiway C T2A T2A T2A T6A T6A	406 (16.0) <sup>1</sup> 25 (1.0) <sup>2</sup> 203 (8.0) <sup>4</sup> 406 (16.0) <sup>1</sup> 25 (1.0) <sup>2</sup>	AC AC PCC AC AC	1964 1973 2001 1964 1973
Taxiway D T3A	229 (9.0)	PCC	1981
Compass Rose Taxiway T4B	406 (16.0) <sup>1</sup>	AC	1964
13 Warm-Up Ramp A1B A1B	406 (16.0) <sup>1</sup> 25 (1.0) <sup>2</sup>	AC AC	1964 1973
31 Warm-Up Ramp A2B A2B	406 (16.0) <sup>1</sup> 25 (1.0) <sup>2</sup>	AC AC	1964 1973
Hoverlane A3B A3B A3B	406 (16.0) <sup>1</sup> 25 (1.0) <sup>2</sup> 102 (4.0) <sup>4</sup>	AC AC AC	1964 1973 2001
Transient Parking Ramp A4B	178 (7.0)	PCC	1964
Charlie Parking Ramp A5B A6B	178 (7.0) 178 (7.0)	PCC PCC	1981 1981
Delta Parking Ramp A7B A8B A9B	178 (7.0) 178 (7.0) 229 (9.0)	PCC PCC PCC	1981 1981 1981
(Continued)			
<sup>1</sup> Thickness includes surface course, base, and subbase. <sup>2</sup> Overlay pavement. <sup>3</sup> Bituminous surface treatment and base. <sup>4</sup> Reconstruction.			



Table A2 (Concluded)			
Pavement Facility (Feature)	Surface Pavement		Construction Date
	Thickness, mm (in.)	Type	
B East parking Ramp A10B	178 (7.0)	PCC	1981
B West parking Ramp A11B	178 (7.0)	PCC	1981
Compass Rose A12B	178 (7.0)	PCC	1981
Alpha Ramp A13B	178 (7.0)	PCC	1981
<sup>1</sup> Thickness includes surface course, base, and subbase. <sup>2</sup> Overlay pavement. <sup>3</sup> Bituminous surface treatment and base. <sup>4</sup> Reconstruction.			

Table A3 Summary of Physical Property Data														
Facility			Overlay Pavement			Pavement			Base			Subbase		
Feature	Identification	Length m (ft)	Width m (ft)	General Condition PCI	Thickness <sup>1</sup> mm (in.)	Description	Flex. Str. <sup>1</sup> MPa (psi)	Thickness <sup>1</sup> mm (in.)	Description	Flex. Str. <sup>1</sup> MPa (psi)	Thickness <sup>1</sup> mm (in.)	Description	Modulus <sup>2</sup> MPa (psi)	Modulus <sup>2</sup> MPa (psi)
Fixed-Wing Facilities														
R1A	Runway 13-31 Overrun	152 (500)	23 (75)	Excellent				102 (4.0)	AC		102 (4.0)	Aggregate Base (GW)	34 <sup>4</sup>	34 <sup>4</sup> Sandy Clay (CL)
R2A	Runway 13-31	152 (500)	23 (75)	Very poor	140 (5.5)	AC		76 (3.0)	AC		610 (24.0)	Gravel (GP)	-- <sup>3</sup>	11 <sup>4</sup> Sandy Clay (CL)
R3A	Runway 13-31	152 (500)	23 (75)	Very poor	140 (5.5)	AC		76 (3.0)	AC		457 (18.0)	Gravel (GP)	-- <sup>3</sup>	9 <sup>4</sup> Sandy Clay (CL)
R4A	Runway 13-31	780 (2,560)	23 (75)	Very poor	140 (5.5)	AC		76 (3.0)	AC		457 (18.0)	Gravel (GP)	-- <sup>3</sup>	11 <sup>4</sup> Sandy Clay (CL)
R5A	Runway 13-31	152 (500)	23 (75)	Poor	140 (5.5)	AC		76 (3.0)	AC		457 (18.0)	Gravel (GP)	-- <sup>3</sup>	11 <sup>4</sup> Sandy Clay (CL)
R6A	Runway 13-31	152 (400)	23 (75)	Poor	140 (5.5)	AC		76 (3.0)	AC		610 (24.0)	Gravel (GP)	147 (21,281)	117 (17,015) Sandy Clay (CL)
R7A	Runway 13-31	43 (140)	38 (126)	Excellent				203 (8.0)	PCC	4 (600)	102 (4.0)	Filter Course	199 (28,812)	107 (15,578) Sandy Clay (CL)
T1A	Taxiway B	320 (1,050)	15 (50)	Failed	25 (1.0)	AC		25 (1.0)	Bituminous Surface Treatment		229 (9.0)	Gravel (GP)	-- <sup>5</sup>	-- <sup>5</sup> Sandy Clay (CL)
T2A	Taxiway C	152 (500)	12 (40)	Excellent				203 (8.0)	PCC	4 (600)	102(4.0)	Filter Course	293 (42,477)	113 (16,377) Sandy Clay (CL)
T6A	Taxiway C	72 (237)	12 (40)	Failed	25 (1.0)	AC		51 (2.0)	AC		152 (6.0)	Stabilized Aggregate	46 <sup>4</sup>	8 <sup>4</sup> Sandy Clay (CL)
(Sheet 1 of 3)														
<sup>1</sup> Values from original construction data and/or measurements recorded in previous investigations. <sup>2</sup> Modulus and/or CBR values used for the structural analysis of the pavement features. <sup>3</sup> Base and subgrade were combined for backcalculating modulus values or for computing CBR values using LOW. <sup>4</sup> CBR values computed using LOW. <sup>5</sup> Beyond the lower limit of LOW.														

Table A3 (Continued)																		
Facility				Overlay Pavement			Pavement			Base			Subbase			Subgrade		
Feature	Identification	Length m (ft)	Width m (ft)	General Condition PCI	Thickness <sup>1</sup> mm (in.)	Description	Flex. Str. <sup>1</sup> MPa (psi)	Thickness <sup>1</sup> mm (in.)	Description	Flex. Str. <sup>1</sup> MPa (psi)	Thickness <sup>1</sup> Min (in.)	Description	Modulus <sup>2</sup> MPa (psi)	Thickness <sup>1</sup> mm (in.)	Description	Modulus <sup>2</sup> MPa (psi)	Description	Modulus <sup>2</sup> MPa (psi)
Fixed-Wing Facilities (Continued)																		
T3A	Taxiway D	191 (627)	12 (40)	Fair				229 (9.0)	PCC	4 (600)	102 (4.0)	Filler Course	103 (14,952)				Sandy Clay (CL)	103 (14,952)
T4B	Compass Rose Taxiway	64 (210)	12 (40)	Very poor				51 (2.0)	AC		152 (6.0)	Stabilized Aggregate	64 <sup>4</sup>	203 (8.0)	Gravel (GP)	9 <sup>4</sup>	Sandy Clay (CL)	9 <sup>4</sup>
T5A	Alpha Lane	823 (2,700)	23 (75)	Failed	25 (1.0)	AC		51 (2.0)	AC		152 (6.0)	Stabilized Aggregate	47 <sup>4</sup>	203 (8.0)	Gravel (GP- GM)	9 <sup>4</sup>	Sandy Clay (CL)	9 <sup>4</sup>
A1B	13 Warm-up	99 (325)	46 (150)	Excellent				203 (8.0)	PCC	4 (600)	102 (4.0)	Filter Course	273 (39,586)	127 (5.0)	Gravel (GP)	273 (39,586)	Sandy Clay (CL)	102 (14,742)
A2B	31 Warm-up	119 (390)	58 (190)	Failed	25 (1.0)	AC		51 (2.0)	AC		152 (6.0)	Stabilized Aggregate	26 <sup>4</sup>	203 (8.0)	Gravel (GP)	4 <sup>4</sup>	Sandy Clay (CL)	4 <sup>4</sup>
A3B	Hoverlane	503 (1,650)	46 (150)	Excellent				102 (4.0)	AC		102 (4.0)	Aggregate Base (GW)	36 <sup>4</sup>	203 (8.0)	Gravel (GP)	12 <sup>4</sup>	Sandy Clay (CL)	12 <sup>4</sup>
A4B	Transient Parking Ramp	68 (225)	59 (193)	Very good				178 (7.0)	PCC	4 (600)	102 (4.0)	Filler Course	68 (9,912)				Sandy Clay (CL)	68 (9,912)
A5B	Charlie Parking Ramp	376 (1,235)	33 (110)	Very good				178 (7.0)	PCC	4 (600)	102 (4.0)	Filler Course	74 (10,701)				Sandy Clay (CL)	74 (10,701)
A6B	Charlie Parking Ramp	503 (1,650)	46 (150)	Very good				178 (7.0)	PCC	4 (600)	102 (4.0)	Filler Course	62 (8,981)				Sandy Clay (CL)	62 (8,981)
A7B	Delta Parking Ramp	149 (487)	33 (110)	Very good				178 (7.0)	PCC	4 (600)	102 (4)	Filler Course	72 (10,397)				Sandy Clay (CL)	72 (10,397)
Sheet 2 of 3																		
Footnotes: 1 Values from original construction data and/or measurements recorded in previous investigations. 2 Modulus and/or CBR values used for the structural analysis of the pavement features. 3 Base and subgrade were combined for backcalculating modulus values or for computing CBR values using LOW. 4 CBR values computed using LOW. 5 Beyond the lower limit of LOW.																		

<sup>1</sup> Values from original construction data and/or measurements recorded in previous investigations.

<sup>2</sup> Modulus and/or CBR values used for the structural analysis of the pavement features.

<sup>3</sup> Base and subgrade were combined for backcalculating modulus values or for computing CBR values using LOW.

<sup>4</sup> CBR values computed using LOW.

<sup>5</sup> Beyond the lower limit of LOW.

Table A3 (Concluded)

Facility		Overlay Pavement			Pavement			Base			Subbase			Subgrade	
Identification	Length m (ft)	Width m (ft)	General Condition PCI	Thickness <sup>1</sup> mm (in.)	Description	Flex. Str. <sup>1</sup> MPa (psi)	Thickness <sup>1</sup> mm (in.)	Description	Flex. Str. <sup>1</sup> MPa (psi)	Thickness <sup>1</sup> mm (in.)	Description	Modulus <sup>2</sup> MPa (psi)	Thickness <sup>1</sup> mm (in.)	Description	Modulus <sup>2</sup> MPa (psi)
<b>Fixed-Wing Facilities (Continued)</b>															
A8B Delta Parking Ramp	149 (487)	33 (110)	Very good				178 (7.0)	PCC	4 (600)	102 (4)	Filler Course	57 (8,226)		Sandy Clay (CL)	57 (8,226)
A9B Delta Parking Ramp	343 1,125	69 (225)	Good				229 (9.0)	PCC	4 (600)	102 (4)	Filler Course	98 (14,284)		Sandy Clay (CL)	98 (14,284)
A10B B East Parking Ramp	148 (487)	33 (110)	Very good				178 (7.0)	PCC	4 (600)	102 (4.0)	Filler Course	67 (9,685)		Sandy Clay (CL)	67 (9,685)
A11B B West Parking Ramp	148 (487)	33 (110)	Very good				178 (7.0)	PCC	4 (600)	102 (4.0)	Filler Course	62 (8,950)		Sandy Clay (CL)	62 (8,950)
A12B Compass Rose	30 (100)	30 (100)	Very good				178 (7.0)	PCC	4 (600)	102 (4.0)	Filler Course	63 (9,630)		Sandy Clay (CL)	63 (9,630)
A13B Alpha Ramp	419 (1,375)	137 (450)	Very good				178 (7.0)	PCC	4 (600)	102 (4.0)	Filler Course	112 (16,218)		Sandy Clay (CL)	112 (16,218)
<b>(Sheet 3 of 3)</b>															

<sup>1</sup> Values from original construction data and/or measurements recorded in previous investigations.<sup>2</sup> Modulus and/or CBR values used for the structural analysis of the pavement features.<sup>3</sup> Base and subgrade were combined for backcalculating modulus values or for computing CBR values using LOW.<sup>4</sup> CBR values computed using LOW.<sup>5</sup> Beyond the lower limit of LOW.

# Appendix B

## Tests and Results

---

### Tests Conducted

The pavements were evaluated based on the results from nondestructive testing utilizing a heavy weight deflectometer (HWD). The test procedures and results are discussed below.

### Nondestructive Tests

#### Test equipment

Nondestructive tests (NDT) were performed on the pavements with the Dynatest model 8081 (HWD). The HWD is an impact load device that applies a single-impulse transient load of approximately 25- to 30-millisecond duration. With this trailer-mounted device, a dynamic force is applied to the pavement surface by dropping a weight onto a set of rubber cushions which results in an impulse loading on an underlying circular plate 300 mm (11.8 in.) in diameter in contact with the pavement. The applied force and the pavement deflections, respectively, are measured with load cells and velocity transducers. The drop height of the weights can be varied from 0 to 399 mm (15.7 in.) to produce a force from 0 to approximately 222 kN (50,000 lb). The system is controlled with a laptop computer that also records the output data. Velocities were measured and deflections computed at the center of the load plate (D1) and at distances of 305 (12), 610 (24), 914 (36), 1219 (48), 1524 (60), and 1828 mm (72 in.) (D2 - D7) from the center of the load plate.

#### Test procedure

On runways and taxiways, deflection basin measurements were made at 30-m (100-ft) intervals on alternate sides of the centerline along the main gear wheel paths. The tests were performed on 3- to 4-m (10- to 12-ft) offsets alternating left and right of the centerline. The parking aprons were tested in a grid pattern of approximately 30-m (100-ft) intervals or at locations that were

selected to ensure that adequate NDT were performed per feature for evaluation purposes. Lines along which the NDT were conducted are indicated in Figure B1. At each test location, pavement deflection measurements were recorded at force levels of approximately 67, 122, 157, or 222 kN (15,000, 25,000, 35,000, or 50,000 lb). Impulse stiffness modulus (ISM) values were then calculated based on the slope of the plot of impulse load versus deflection at the first sensor (D1), for the maximum force level.

## NDT Analysis

The NDT results or ISM data for each facility were grouped according to different pavement features. Figures B2 through B21 graphically show the ISM test results. A representative basin for each feature was determined using the computerized Layered Elastic Evaluation Program (LEEP). Table B1 shows the representative basins for each feature as determined from the NDT.

Representative basins were used to determine section modulus values of the various layers within the pavement structure in each feature. Deflection basins were input to a multi-layered, linear elastic backcalculation program to determine the surface, base, and subgrade modulus values. The program determines a set of modulus values that provide the best fit between a measured (NDT) deflection basin and a computed (theoretical) deflection basin. Table B2 presents a summary of the backcalculated modulus values based on the representative basins for each pavement section.

Where mean ISM values (as shown in Table B1) were less than 70 MN/m (400 kips/in.), the Low Volume Airfield Pavement Procedure (Bush 1986) computer program (LOW) was used to evaluate the pavements. Twelve features were in this category. ISM and layer thicknesses were input into LOW to determine the equivalent base and subgrade California Bearing Ratio (CBR). Layer thicknesses and respective CBR values were then input into the computer program APE (Computer-Aided Airfield Pavement Evaluation) to compute the load-carrying capacity in terms of PCN of the pavement feature and the overlay thickness requirements. Table B3 shows the CBR values determined from LOW.

Modulus values for AC surface layers can be determined using three methods: (a) use the surface temperature at the time of testing and the previous 5-day mean air temperature, (b) backcalculate the modulus values using the HWD deflection basins, or (c) determine the design modulus from past temperature data. All three methods of determining the AC modulus values are described in UFC 3-260-03 (Headquarters, Departments of the Army, the Air Force, and the Navy April 2001a). All pavements have been evaluated for a design life of 20 years. The modulus of an AC layer is temperature dependent; therefore, seasonal variation is considered by using a design modulus based on historical temperature data. From the climatological table (Table A1), an average daily maximum temperature of 27°C (80°F) and an average daily mean of 21°C (69°F) for June (hottest month) were used in determining the design AC modulus. For a loading frequency of 2 Hz for taxiways and aprons, the design AC modulus

is 885 MPa (128,337 psi) for a loading frequency of 10 Hz for the runway, the design AC modulus is 1556 MPa (225,719 psi). The design AC modulus along with the backcalculated values for the base and subgrade layers were used to determine the structural capacity of the AC pavement features.

Modulus values for PCC pavements can be backcalculated using the HWD deflection basins or a design modulus for the PCC can be used. In the evaluation of a rigid pavement, the design modulus should be used for the PCC layer along with the backcalculated values for the subgrade layers. The backcalculated PCC modulus values shown in Table B2 for features T2A, A1B, and A12B are greater than the default range of 17 237 to 68 947 MPa (2,500,000 to 10,000,000 psi) recommended in UFC 3-260-03 (Headquarters, Departments of the Army, Navy, and the Air Force, and the Navy 2001a). This manual also recommends a modulus of 34 474 MPa (5,000,000 psi) for a PCC layer in good condition.




Figure B1. NDT test locations/direction






Figure B2. ISM profile, Runway 13-31, Features R1A thru R7A




Figure B3. ISM profile, Taxiway Bravo, Feature T1A




Figure B4. ISM profile, Taxiway Charlie, Feature T2A




Figure B5. ISM profile, Taxiway Charlie, Feature T6A




Figure B6. ISM profile, Taxiway Delta, Feature T3A




Figure B7. ISM profile, Compass Rose Taxiway, Feature T4B




Figure B8. ISM profile, Alpha Lane, Features T5A




Figure B9. ISM profile, 13 Warm-up Ramp, Feature A1B




Figure B10. ISM profile, 31 Warm-up Ramp, Feature A2B




Figure B11. ISM profile, Hoverlane, Feature A3B




Figure B12. ISM profile, Transient Parking Ramp, Feature A4B




Figure B13. ISM profile, Charlie Parking Ramp, Feature A5B




Figure B14. ISM profile, Charlie Parking Ramp, Feature A6B




Figure B15. ISM profile, Delta Parking Ramp, Feature A7B




Figure B16. ISM profile, Delta Parking Ramp, Feature A8B




Figure B17. ISM profile, Delta Parking Ramp, Feature A9B






Figure B18. ISM profile, b East Parking Ramp, Feature A10B




Figure B19. ISM profile, B West Parking Ramp, Feature A11B




Figure B20. ISM profile, Compass Rose, Feature A12B




Figure B21. ISM profile, Alpha Ramp, Feature A13B

Table B1									
NDT Test Results, Representative Basins									
Feature	ISM MN/m (kips/in.)	Load kN (lb)	Deflection, $\mu$ m (mils)						
			D1	D2	D3	D4	D5	D6	D7
Runway 13-31									
R1A	51 (289)	90 (20,141)	1773 (69.8)	950 (37.4)	462 (18.2)	290 (11.4)	208 (8.2)	157 (6.2)	124 (4.9)
R2A	63 (360)	89 (20,093)	1422 (56.0)	826 (32.5)	457 (18.0)	282 (11.1)	193 (7.6)	147 (5.8)	117 (4.6)
R3A	68 (386)	93 (20,463)	1346 (53.0)	909 (35.8)	574 (22.6)	363 (14.3)	244 (9.6)	168 (6.6)	137 (5.4)
R4A	61 (350)	93 (20,490)	1483 (58.4)	808 (31.8)	414 (16.3)	244 (9.6)	168 (6.6)	127 (5.0)	102 (4.0)
R5A	67 (382)	96 (21,090)	1400 (55.1)	734 (28.9)	381 (15.0)	216 (8.5)	150 (5.9)	112 (4.4)	86 (3.4)
R6A	73 (414)	95 (21,388)	1313 (51.7)	602 (23.7)	302 (11.9)	185 (7.3)	130 (5.1)	102 (4.0)	84 (3.3)
R7A	292 (1,668)	96 (21,511)	328 (12.9)	302 (11.9)	254 (10.0)	203 (8.0)	157 (6.2)	114 (4.5)	81 (3.2)
Taxiway Bravo									
T1A	22 (128)	54 (12,049)	2393 (94.2)	1069 (42.1)	455 (17.9)	259 (10.2)	229 (6.9)	127 (5.0)	97 (3.8)
Taxiway Charlie									
T2A	482 (2,751)	229 (51,436)	475 (18.7)	439 (17.3)	394 (15.5)	351 (13.8)	310 (12.2)	269 (10.6)	229 (9.0)
T6A	46 (260)	63 (14,210)	1389 (54.7)	835 (32.9)	442 (17.4)	269 (10.6)	183 (7.2)	137 (5.4)	102 (4.0)
Taxiway Delta									
T3A	365 (2,083)	220 (49,581)	605 (23.8)	559 (22.0)	493 (19.4)	422 (16.6)	351 (13.8)	284 (11.2)	229 (9.0)
Compass Rose Taxiway									
T4B	40 (226)	65 (14,659)	1646 (64.8)	879 (34.6)	401 (15.8)	234 (9.2)	170 (6.7)	132 (5.2)	107 (4.2)
Alpha Lane									
T5A	53 (305)	64 (14,476)	1204 (47.4)	663 (26.1)	330 (13.0)	206 (8.1)	147 (5.8)	114 (4.5)	102 (3.5)
13 Warm-up Ramp									
A1B	476 (2,717)	230 (51,627)	483 (19.0)	450 (17.7)	406 (16.0)	361 (14.2)	315 (12.4)	267 (10.5)	224 (8.8)
31 Warm-up Ramp									
A2B	32 (180)	64 (14,317)	2017 (79.4)	953 (37.5)	414 (16.3)	127 (9.3)	152 (6.0)	122 (4.8)	97 (3.8)
Hoverlane									
A3B	61 (348)	60 (13,598)	993 (39.1)	587 (23.1)	302 (11.9)	185 (7.3)	127 (5.0)	178 (3.7)	76 (3.0)
Transient Parking Ramp									
A4B	178 (1,019)	219 (49,323)	1229 (48.4)	1097 (43.2)	932 (36.7)	765 (30.1)	612 (24.1)	462 (18.2)	325 (12.8)
Charlie Parking Ramp									
A5B	214 (1,221)	218 (49,104)	1021 (40.2)	950 (37.4)	826 (32.5)	691 (27.2)	551 (21.7)	419 (16.5)	302 (11.9)
A6B	121 (1,073)	216 (48,505)	1148 (45.2)	1057 (41.6)	914 (36.0)	767 (30.2)	620 (24.4)	488 (19.2)	363 (14.3)
(Continued)									

Table B1 (Concluded)									
Feature	ISM MN/m (kips/in.)	Load kN (lb)	Deflection, $\mu\text{m}$ (mils)						
			D1	D2	D3	D4	D5	D6	D7
Delta Parking Ramp									
A7B	241 (1,376)	215 (48,282)	892 (35.1)	950 (37.4)	815 (32.1)	673 (26.5)	538 (21.2)	414 (16.3)	305 (12.0)
A8B	207 (1,184)	213 (47,833)	1026 (40.4)	1184 (46.6)	1024 (40.3)	853 (33.6)	676 (26.6)	511 (20.1)	361 (14.2)
A9B	355 (2,026)	219 (49,228)	490 (24.3)	457 (22.4)	307 (19.5)	218 (16.7)	150 (14.0)	99 (11.6)	56 (9.5)
B East Parking Ramp									
A10B	194 (1,108)	212 (47,774)	1095 (43.1)	1022 (40.2)	881 (34.7)	714 (28.1)	587 (23.1)	452 (17.8)	328 (12.9)
B West Parking Ramp									
A11B	184 (1,050)	211 (47,460)	1148 (45.2)	1054 (41.5)	919 (36.2)	772 (30.4)	625 (24.6)	483 (19.0)	356 (14.0)
Compass Rose									
A12B	257 (1,468)	223 (50,042)	866 (34.1)	803 (31.6)	714 (28.1)	622 (24.5)	528 (20.8)	442 (17.4)	361 (14.2)
Alpha Ramp									
A13B	302 (1,724)	221 (49,661)	732 (28.8)	655 (25.8)	554 (21.8)	457 (18.0)	366 (14.4)	284 (11.2)	213 (8.4)

<b>Table B2 Summary of Modulus Values<sup>1</sup></b>				
<b>Feature</b>	<b>Surface Modulus MPa (psi)<sup>1</sup></b>	<b>Base Modulus MPa (psi)<sup>1</sup></b>	<b>Subbase Modulus MPa (psi)<sup>1</sup></b>	<b>Subgrade Modulus MPa (psi)<sup>1</sup></b>
<b>PCC Pavements</b>				
R7A	25 531 (3,702,975)	199 (28,812) <sup>2</sup>	--	107 (15,578)
T2A	103 421 (15,000,000)	293 (42,477) <sup>2</sup>	--	113 (16,377)
T3A	49 990 (7,105,409)	--	--	103 (14,952)
A1B	127 888 (18,549,542)	273 (39,586) <sup>2</sup>	--	102 (14,742)
A4B	31 139 (4,516,324)	--	--	68 (9,912)
A5B	41 618 (6,036,187)	--	--	74 (10,701)
A6B	35 968 (5,216,678)	--	--	62 (8,981)
A7B	49 732 (7,212,975)	--	--	72 (10,397)
A8B	42 929 (6,226,351)	--	--	57 (8,226)
A9B	50 063 (7,261,050)	--	--	98 (14,284)
A10B	38 082 (5,523,290)	--	--	67 (9,685)
A11B	38 411 (5,571,095)	--	--	62 (8,950)
A12B	80 226 (11,635,792)	--	--	66 (9,630)
A13B	57 670 (8,364,400)	--	--	111 (16,218)
<b>AC Pavements<sup>3</sup></b>				
R1A <sup>5</sup>	1953 (283,194)	111 (16,154) <sup>2</sup>	--	72 (10,406) <sup>2</sup>
R2A <sup>5</sup>	607 (88,079)	94 (13,620)	--	75 (10,899)
R3A <sup>5</sup>	261 (37,833)	207 (30,000)	--	51 (7,341)
R4A <sup>5</sup>	589 (124,571)	112 (16,180)	--	74 (10,744)
R5A <sup>5</sup>	555 (80,454)	105 (15,166)	--	103 (14,953)
R6A	474 (68,680)	147 (21,281)	--	117 (17,015)
T1A <sup>5</sup>	7822 (1,134,507)	377 (54,726)	--	64 (9,350)
T4B <sup>5</sup>	8317 (1,206,289)	160 (23,267)	58 (8,386) <sup>4</sup>	58 (8,386) <sup>4</sup>
T5B <sup>5</sup>	3402 (493,447)	122 (17,694)	75 (10,949) <sup>4</sup>	75 (10,949) <sup>4</sup>
<b>(Continued)</b>				
<sup>1</sup> Backcalculated modulus values using WESDEF. <sup>2</sup> Filter or base course and subbase were combined. <sup>3</sup> AC modulus based on temperature at the time of testing. <sup>4</sup> Based on subbase and subgrade combined. <sup>5</sup> ISM was < 400; therefore, LOW was used to compute base and subgrade CBR.				

<b>Table B2 (Concluded)</b>				
<b>Feature</b>	<b>Surface Modulus MPa (psi)<sup>1</sup></b>	<b>Base Modulus MPa (psi)<sup>1</sup></b>	<b>Subbase Modulus MPa (psi)<sup>1</sup></b>	<b>Subgrade Modulus MPa (psi)<sup>1</sup></b>
<b>AC Pavements</b>				
T6A <sup>5</sup>	2219 (321,843)	162 (23,524)	59 (8,510) <sup>4</sup>	59 (8,510) <sup>4</sup>
A2B <sup>5</sup>	302 (43,821)	164 (23,756)	59 (8,624) <sup>4</sup>	59 (8,624) <sup>4</sup>
A3B <sup>5</sup>	1095 (158,786)	206 (30,000) <sup>2</sup>	206 (30,000) <sup>2</sup>	75 (10,872)
<sup>1</sup> Backcalculated modulus values using WESDEF. <sup>2</sup> Filter or base course and subbase were combined. <sup>3</sup> AC modulus based on temperature at the time of testing. <sup>4</sup> Based on subbase and subgrade combined. <sup>5</sup> ISM was < 400; therefore, LOW was used to compute base and subgrade CBR.				

**Table B3**  
**Summary of CBR Values Determined from LOW**

Feature	Mean ISM MN/m (kips/in.)	Pavement Age, Years	Surface Thickness mm (in.)	Base Thickness mm (in.)	Subbase Thickness mm (in.)	Base CBR, %	Subbase CBR, %	Subgrade CBR, %
R1A	51 (289)	2	102 (4.0)	178 (7.0)		34		6
R2A	63 (360)	16	216 (8.5)					11
R3A	68 (386)	16	216 (8.5)					9
R4A	61 (350)	16	216 (8.5)					11
R5A	67 (382)	16	216 (8.5)					11
R6A	72 (414)	16	216 (8.5)					11
T1A	22 (128)	29	51 (2.0)	229 (9.0)		-- <sup>1</sup>		-- <sup>1</sup>
T4B	40 (226)	38	51 (2.0)	152 (6.0)		64		9
T5A	53 (305)	29	76 (3.0)	152 (6.0)		47		9
T6A	46 (260)	29	76 (3.0)	152 (6.0)		46		8
A2B	32 (180)	29	76 (3.0)	152 (6.0)		26		4
A3B	61 (348)	2	102 (4.0)	102 (4.0)		36		12

<sup>1</sup> Beyond the lower limit of LOW.

# Appendix C

## Pavement Condition Survey and Results

---

### Pavement Condition Survey

A pavement condition survey is a visual inspection of the airfield pavements to determine the present surface condition. The condition survey consists of inspecting the pavement surface for various types of distress, determining the severity of each distress, and measuring the quantity of each distress. The estimated quantities and severity of each distress type are used to compute the PCI for each feature. The PCI is a numerical indicator based on a scale from 0 to 100 and is determined by measuring pavement surface distress that reflects the surface condition of the pavement. Pavement condition ratings (from excellent to failed) are assigned to different levels of PCI values. These ratings and their respective PCI value definitions are shown in Figure C1. The distress types, severity levels, methods of survey, and PCI calculations are described in ASTM D5340-93.

The PCI and estimated distress quantities are determined for each feature. The information is based on inspection of a selected number of sample units. Sample units are subdivisions of a feature used exclusively to facilitate the inspection process and reduce the effort needed to determine distress quantities and the PCI. Each feature was divided into sample units. The sample units for AC pavement features were approximately 465 sq m (5,000 sq ft). A statistical sampling technique was used to determine the number of sample units to be inspected to provide a 95 percent confidence level. Sample units were chosen along the centerline of the runway and taxiways and randomly on the aprons. The stationing and direction of survey are shown in Figure B1. Sample unit locations for the runway feature R7A is shown in Figure C2. Sample unit locations for the PCC taxiway features T2A and T3A are shown in Figure C3. Sample unit locations for the apron/ramp areas are shown in Figures C4-C11. The surveyed sample units are circled. After the sample units were inspected, the mean PCI of all sample units within a feature was calculated and the feature was rated as to its condition: excellent, very good, good, fair, poor, very poor, or failed.



## Analysis of PCI Data

The distress information collected during the survey was used with the Micro PAVER computer program to estimate the quantities of distress types for each feature. This information is presented along with the PCI, general rating, and distress mechanism (load, climate, or other) in Appendix E. Photos C1 through C10 show various types of distresses observed during the survey.

AR 420-72 (Headquarters, Department of the Army 2000) requires that all airfield pavements be maintained at or above the following PCI ranges:

- All runways > 70
- All primary taxiways  $\geq 60$
- All aprons and secondary taxiways > 55

AR 420-72 (Headquarters, Department of the Army 2000) also requires that the following PCI range for airfield pavements shall be used for the Installation Status Report (ISR) rating:

- $70 < \text{PCI} \leq 100$  equals an ISR Green rating
- $55 < \text{PCI} \leq 70$  equals an ISR Amber rating
- $0 < \text{PCI} \leq 55$  equals an ISR Red rating

The PCI for each sample unit inspected was calculated and stored on a Micro PAVER file for BAAF. The mean PCI for each feature was then calculated to determine the general condition or rating of the feature as shown in Figure C12. A comparison of the 2002, 1995, and 1993 PCI results is summarized in Table C1. The PCI of five runway features decreased from twenty-six to thirty-five points during the 1995 to 2002 period. This loss in PCI points for each feature (R2A-R6A) is due to additional and/or more severe alligator cracking, block cracking, linear cracking, and rutting. The PCI of R1A increased by eighty-nine points due to surface reconstruction. The PCI of all but one of the taxiway features remained about the same during the 1995 to 2002 period. One taxiway feature (T2A) had an increase in PCI of eighty-seven points, which was attributed to reconstruction in 2001. The PCI of all but two of the apron/ramp features remained about the same during the 1995 to 2002 period. Features A1B and A3B had an increase in PCI of eighty-seven and eighty-nine points, respectively. These increases are attributed to reconstruction in 2001.








PAVEMENT CONDITION INDEX (PCI)		PAVEMENT CONDITION RATING
100		<b>EXCELLENT</b>
86		
85		<b>VERY GOOD</b>
71		
70		<b>GOOD</b>
56		
55		<b>FAIR</b>
41		
40		<b>POOR</b>
26		
25		<b>VERY POOR</b>
11		
10		<b>FAILED</b>
0		

Figure C1. Scale for pavement condition rating




Figure C2. Sample unit layout, Runway 13-31, feature R7A




Figure C3. Sample unit layout, Taxiways Charlie and Delta, features T2A and T3A




Figure C4. Sample unit layout, 13 Warm-up Ramp, feature A1B




Figure C5. Sample unit layout, 31 Warm-up Ramp, Transient Parking Ramp, and the Compass Rose, features A2B, A4B, and A12B, respectively




Figure C6. Sample unit layout, Charlie Parking Ramp, feature A5B




Figure C7. Sample unit layout, Charlie Parking Ramp, feature A6B






Figure C8. Sample unit layout, Delta Parking Ramp, features A7B and A8B





Figure C9. Sample unit layout, Delta Parking Ramp, feature A9B

FEATURE A10B



FEATURE A11B





Figure C10. Sample unit layout, b East and B West Parking Ramps, feature A10B and A11B, respectively






Figure C12. Pavement condition rating summary

<b>Table C1 Comparison of 1993, 1995, and 2002 PCI Surveys</b>						
<b>Feature</b>	<b>1993 PCI</b>	<b>1995 PCI</b>	<b>2002 PCI</b>	<b>2002 Rating</b>	<b>Change in PCI From 1995 to 2002 (+ or -)</b>	<b>Pavement Type</b>
<b>Runway</b>						
R1A	3	3	92	Excellent	89	AC
R2A	74	58	25	Very poor	-33	AC
R3A	70	59	14	Very poor	-35	AC
R4A	72	55	22	Very poor	-33	AC
R5A	71	55	26	Poor	-29	AC
R6A	74	59	33	Poor	-26	AC
R7A	--	--	93	Excellent	--	PCC
<b>Taxiways</b>						
T1A	2	3	2	Failed	-1	AC
T2A	17	3	90	Excellent	+87	AC
T3A	68	49	50	Fair	+1	PCC
T4B	28	22	19	Very poor	-3	AC
T5A	24	5	5	Failed	--	AC
T6A	17	3	5	Failed	+2	AC
<b>Aprons and Ramps</b>						
A1B	17	5	92	Excellent	+87	PCC
A2B	2	3	5	Failed	+2	AC
A3B	26	4	93	Excellent	+89	AC
A4B	97	82	82	Very good	--	PCC
A5B	97	83	84	Very good	+1	PCC
A6B	95	76	78	Very good	+2	PCC
A7B	94	80	80	Very good	--	PCC
A8B	93	86	80	Very good	-6	PCC
A9B	83	66	64	Good	-2	PCC
A10B	88	85	84	Very good	-1	PCC
A11B	84	81	85	Very good	+4	PCC
A12B	88	79	84	Very good	+5	PCC
A13B	100	92	81	Very good	-9	PCC



Photo C1. Alpha Ramp, Feature A13B, medium-severity longitudinal crack



Photo C2. Alpha Lane, Feature T5A, high-severity block cracking and weathering





Photo C3. Taxiway Bravo, Feature T1A, high-severity rutting



Photo C4. Runway 13-31, Feature R6A, low-severity slippage cracks





Photo C5. Runway 13-31, Feature R7A, new PCC



Photo C6. Charlie Ramp, Feature A5B, medium-severity fault



Photo C7. Delta Ramp, Feature A9B, high-severity corner spalling



Photo C8. Delta Ramp, Feature A7B, high-severity "D" cracking





Photo C9. Alpha Ramp, Feature A13B, low-severity "D" cracking



Photo C10. Runway 13-31, Feature R2A, high-severity patch of slippage damage

# Appendix D

## Structural Analyses

---

### General

The performance of the airfield pavement facilities was analyzed for the traffic shown in Table D1.

The operational ACN values determined for the C-130 and CH-47 aircrafts are shown in Table D2 for the four subgrade strength categories.

In a wartime scenario, aircraft may be required to operate at weights that exceed normal peacetime loads. These aircraft would have a higher ACN, would cause more damage, and reduce the life of the pavement. A mobilization ACN can be determined from the appropriate ACN-PCN curve presented in ETL 1110-3-394 (Headquarters, Department of the Army 1991). Typical ACN-PCN curves for the C-130 and CH-47 aircrafts are shown in Figures D1 and D2, respectively. For contingency planning, it is often necessary to determine the largest aircraft that can safely land on an airfield. Runway length is a critical factor in this determination. Minimum take-off distances for maximum take-off weights of aircraft are also given in ETL 1110-3-394 (Headquarters, Department of the Army 1991). For a specified aircraft, the ACN can be determined from the ACN-PCN curve and then the effect of the higher loads on the airfield can be determined from the ACN/PCN ratio. Specific aircraft mobilization traffic requirements are contained in classified mobilization plans and are not included in this report.

### ACN-PCN Method of Reporting Pavement Structural Condition

The ACN-PCN method is structured so that the structural evaluation of a pavement for a particular aircraft can be accomplished by using the ratio of the aircraft ACN to the pavement PCN. For a given pavement life and a given number of operations of a particular aircraft, there is a relationship between the ACN/PCN ratio and the percent of pavement life used by the applied traffic. For a given ACN/PCN ratio, a relationship exists for the number of operations that will produce failure of the pavement. These relationships provide a method for

evaluating a pavement for allowable load depending on an acceptable degree of damage to the pavement or an allowable number of operations of a particular aircraft to cause failure of a pavement. For aircraft having an ACN equal to the PCN, the predicted failure of the pavement would equal the design life of the pavement. Aircraft having ACN's higher than the pavement PCN would overload the pavement and decrease the life of the pavement. Likewise if the ACN of the operational aircraft were less than the pavement PCN, the life of the pavement would be greater than the design life. If the operational ACN is greater than the pavement PCN and a decrease in pavement life is not acceptable, then structural improvement of the pavement is required to bring the pavement PCN up to or greater than the operational ACN.

## PCN Analysis

Modulus values shown in Appendix B were input into the computerized Layered Elastic Evaluation Program (LEEP) to determine the load-carrying capacity of each pavement feature in accordance with UFC 3-260-03 (Headquarters, Departments of the Army, Navy, and the Air Force 2001a). Using the design aircraft and traffic levels for normal operations, a PCN was determined for each pavement feature. The PCN is determined using the allowable gross aircraft load and the subgrade strength category. To determine the subgrade category, backcalculated subgrade moduli were converted to CBR values using the correlation  $E = 1500 \text{ (CBR)}$ . Table D3 presents a summary of the evaluation of each pavement feature in terms of allowable gross aircraft loadings, PCN, and overlay thicknesses required to increase the structural capacity such that the mission traffic can be supported ( $\text{PCN} \geq \text{operational ACN}$ ). The Airfield Pavement Evaluation Chart (APEC) presented in Illustration 1, Executive Summary, shows a layout of the airfield pavements and corresponding PCN for each facility.

The PCN codes and PCI for each feature were analyzed to establish ISR ratings listed in Table 3-1. An ISR Rating for each pavement facility is shown in Illustration 2, Executive Summary. AR 420-72 (Headquarters Department of the Army 2000) requires that the following ACN/PCN ratios be used in determining ISR ratings for airfield pavement facilities.

$\text{ACN/PCN} \leq 1.0$  equals an ISR Green rating

$1.0 < \text{ACN/PCN} \leq 1.5$  equals an ISR Amber rating

$\text{ACN/PCN} > 1.5$  equals an ISR Red rating

For those features having a  $\text{PCN} < \text{the required operational ACN}$ , the additional pavement thickness (overlay) needed to support the mission traffic was computed. Although the required increase in pavement strength is presented as an overlay thickness, several other approaches could be considered. A detailed analysis will be required to select and design the most cost-effective repair or improvement alternative. It should be noted that although less than 102 mm (4-in.) -thick AC overlay requirements are indicated in Table D3, the following minimum thicknesses are recommended in UFC 3-260-2 (Headquarters, Departments of the Army, Navy, and the Air Force 2001b):

- a. 51 mm (2-in.) -thick minimum AC overlay over AC pavements.
- b. 102 mm (4-in.) -thick minimum AC overlay over PCC pavements.
- c. 152 mm (6-in.) -thick minimum PCC partially or nonbonded overlay.
- d. 51 mm (2-in.) -thick minimum PCC fully bonded overlay over PCC pavements.

These minimum overlay requirements are required to control the degree of cracking which will occur in the base pavement (existing pavement) due to the application of the design traffic. If those features needing structural improvements are not upgraded in a timely manner pavement may deteriorate rapidly and result in damage to all pavement layers and an increase in cost for the necessary improvements. Excessive damage may also result in lengthy closures of the pavement facility.

The PCN codes for the weakest feature within each pavement facility are shown in Table D4. The PCN code includes the PCN numerical value, pavement type, subgrade category, allowable tire pressure, and method used to determine the PCN. An example of a PCN code is: 30/F/A/W/T, with 30 expressing the numerical PCN value, F indicating a flexible pavement, A indicating high strength subgrade, W indicating high-allowable tire pressure, and T indicating that the PCN value was obtained by a technical evaluation. Table D5 presents a description of the letter codes comprising the PCN code. Each PCN assumes that only the design aircraft will be used for the stated number of passes. Theoretically, if the PCN is equal to the ACN, the pavement should perform satisfactorily and require only routine maintenance through the length of the analysis period. There may be situations when it is necessary to overload a pavement, i.e., the ACN is greater than the PCN. Examples are emergency landings, short-term contingencies, exercises, and air shows. Pavements can usually support some overload; however, pavement life can be reduced. If the PCN were less than the ACN, the ACN/PCN ratio would be greater than 1 and the pavement would be expected to fail before reaching the end of the analysis period. As a general rule, ACN/PCN ratios of up to 1.25 have minimal impact on pavement life. If the ACN/PCN ratio is between 1.25 and 1.50, aircraft operations should be limited to 10 passes and the pavement inspected after each operation. Aircraft operations resulting in an ACN/PCN ratio over 1.50 should not be allowed except for emergencies. An example of how to use the ACP/PCN method to determine if an aircraft will overload a pavement is shown below.

## Example Problem

Runway 13-31, taxiway C or D, and the Charlie Parking Ramp must be used for 1,000 passes of a C-130 aircraft operating at a take-off weight of 49 900 kg (110,000 lb). Find the weakest features on each facility and determine if they can support this traffic?

## Solution

From Table D3, determine the PCN for the weakest feature on R/W 13-31, and for taxiways C and D, and for Charlie Parking Ramp; from Figure D1 determine the ACN of a 49 900 kg (110,000 lb) C-17, and then calculate the ACN/PCN ratio using the appropriate PCN from Table D3.

*a.* Runway 13-31.

Weakest feature is R1A (see Table D3)

PCN for R1A = 11/F/C/W/T

ACN for a 50 900 kg (110,000 lb) C-130 on a low strength subgrade = 21/F/C/W/T (see Figure D1).

ACN/PCN ratio is 21/11 or 1.9; therefore R/W 15-33 should only be used in an emergency.

*b.* Taxiway C.

Weakest feature is T6A

PCN for T6A = 8/F/B/W/T

ACN for a C-130 on a medium strength subgrade = 19/F/B/W/T (see Figure D1).

ACN/PCN ratio is 19/8 or 2.4; therefore aircraft operations on T6A should also be limited to emergencies.

*c.* Taxiway D.

PCN for T3A = 32/R/C/W/T

ACN for a C-130 on a low strength subgrade = 23/R/C/W/T (see Figure D1).

ACN/PCN ratio is 23/32 or 0.7; therefore T3A should perform satisfactorily.

*d.* Charlie Parking Ramp.

Weakest feature is A6B.

PCN for A6B = 21/R/D/W/T

ACN for a C-130 on a low strength subgrade = 24/R/D/W/T (see Figure D1).

ACN/PCN ratio is 24/21 or 1.1; therefore the overload on A6B will have minimal impact on the pavement life.

A summary of the evaluation of the controlling feature of each pavement facility in terms of PCN for the thaw-weakened period (November through March) is shown in Table D4. When a pavement is not properly designed and constructed to withstand the detrimental effects of winter, one or both of the following will occur: nonuniform heave due to ice lenses or loss of strength during the thaw period. Thaw-weakened periods, which generally occur during the time period of November through March, are based on the climatological data shown in Table A1. During this period, several to many cycles of freezing and

thawing will occur. Loss of strength will take place during thaw periods in those pavements that have not been properly designed and constructed to prevent such loss. The degree of strength loss depends upon the depth of frost and subsequent thawing. The depth of frost penetration 635 mm (25 in.) was determined from the climatological data summary for BAAF. Typical soils in the area are high frost susceptible and have a frost code of F-3. The base and subbase materials are frost susceptible and have a frost code of F-1. PCN's for the thaw-weakened periods are provided as guidance to the airfield operator for managing airfield operations during the November through March time frame.






Figure D1. ACN-PCN curve for C-130




Figure D2. ACN-PCN curve for CH-47

<b>Table D1 Determination of Critical Aircraft and Design Traffic</b>			
<b>Fixed-Wing Pavements</b>			
<b>Fixed-Wing Aircraft</b>	<b>Gross Weight kg (lb)</b>	<b>20-year Projected Aircraft Passes</b>	<b>20-year Equivalent C-130 Passes</b>
C-130	70 300 (155,000)	6,000	6,000
20-year Total Equivalent C-130 passes @ 70 300 (155,000) = 6,000			
<b>Rotary-Wing Pavements</b>			
<b>Fixed-Wing Aircraft</b>	<b>Gross Weight kg (lb)</b>	<b>20-year Projected Aircraft Passes</b>	<b>20-year Equivalent CH-47 Passes</b>
CH-47	22 700 (50,000)	50,000	50,000
20-year Total Equivalent CH-47 passes @ 22 700 (50,000) = 50,000			

**Table D2**  
**Determination of ACN Values for the Critical Aircraft**

Fixed-Wing AC Pavements			
Design Aircraft	Weight kg (lb)	Subgrade Category <sup>1</sup>	ACN or Required PCN
C-130	70 300 (155,000)	A B C D	24 28 30 36
Fixed-Wing PCC Pavements			
Design Aircraft	Weight kg (lb)	Subgrade Category <sup>1</sup>	ACN or Required PCN
C-130	70 300 (155,000)	A B C D	27 30 33 35
Rotary-Wing AC Pavements			
Design Aircraft	Weight kg (lb)	Subgrade Category <sup>1</sup>	ACN or Required PCN
CH-47	22 700 (50,000)	A B C D	7 9 10 12
Rotary-Wing PCC Pavements			
Design Aircraft	Weight kg (lb)	Subgrade Category <sup>1</sup>	ACN or Required PCN
CH-47	22 700 (50,000)	A B C D	9 10 11 11

<sup>1</sup> See Table D5 for subgrade category.

**Table D3**  
**Allowable Gross Aircraft Loads and Overlay Requirements for the Projected Day-To-Day Traffic**

Pavement Facility	Feature	Test Number or Station m (ft)	Type Traffic Area	Subgrade Strength <sup>1</sup> CBR, % or k, kPa/mm (psi/in.)	Design Aircraft <sup>2</sup>				Allowable Gross Load Mg (kips)	PCN	Theoretical Overlay Requirements, mm (in.)		
					Aircraft	Weight Kg (lb)	Passes	ACN			AC	PCC Partial Bond	PCC No Bond
Fixed-wing Facilities													
Runway 13-31	R1A <sup>3</sup>	0+00-1+52 (0+00-5+00)	A	6	C-130	70 300 (155,000)	6,000	30/F/C/W/T	-- <sup>4</sup>	11/F/C/W/T	132 (5.2) <sup>7</sup>	NA	-- <sup>5</sup>
	R2A <sup>3</sup>	1+52-3+05 (5+00-10+00)	A	11	C-130	70 300 (155,000)	6,000	28/F/B/W/T	46 (102)	18/F/B/W/T	20 (0.8) <sup>7</sup>	NA	-- <sup>5</sup>
	R3A <sup>3</sup>	3+05-4+57 (10+00-15+00)	A	9	C-130	70 300 (155,000)	6,000	28/F/B/W/T	38 (83)	14/F/B/W/T	46 (1.8)	NA	-- <sup>6</sup>
	R4A <sup>3</sup>	4+57-12+37 (15+00-40+60)	A	11	C-130	70 300 (155,000)	6,000	28/F/B/W/T	46 (102)	18/F/B/W/T	20 (0.8) <sup>7</sup>	NA	-- <sup>5</sup>
	R5A <sup>3</sup>	12+37-13+90 (40+60-45+60)	A	11	C-130	70 300 (155,000)	6,000	28/F/B/W/T	46 (102)	18/F/B/W/T	20 (0.8) <sup>7</sup>	NA	-- <sup>5</sup>
	R6A	13+90-15+12 (45+60-49+60)	A	11	C-130	70 300 (155,000)	6,000	28/F/B/W/T	46 (102)	18/F/B/W/T	20 (0.8) <sup>7</sup>	NA	-- <sup>5</sup>
Taxiway C	R7A	15+12-15+54 (49+60-51+00)	A	66 (243)	C-130	70 300 (155,000)	6,000	30/R/B/W/T	61 (134)	26/R/B/W/T	NA	122 (4.8)	160 (6.3)
	T2A	0+00-1+52 (0+00-5+00)	A	86 (318)	C-130	70 300 (155,000)	6,000	30/R/B/W/T	64 (141)	27/R/B/W/T	NA	109 (4.3)	142 (5.6)
	T6A <sup>3</sup>	1+52-2+25 (5+00-7+37)	A	8	C-130	70 300 (155,000)	6,000	28/F/B/W/T	-- <sup>4</sup>	8/F/B/W/T	130 (5.1)	NA	-- <sup>5</sup>
	T3A	0+00-1+91 (0+00-6+27)	A	38 (141)	C-130	70 300 (155,000)	6,000	33/R/C/W/T	68 (151)	32/R/C/W/T	NA	99 (3.9)	135 (5.3)
13 Warm-up	A1B	1-5	B	82 (301)	C-130	70 300 (155,000)	6,000	30/R/B/W/T	67 (147)	28/R/B/W/T	NA	97 (3.8)	130 (5.1)
31 Warm-up	A2B <sup>3</sup>	1-5	B	4	C-130	70 300 (155,000)	6,000	36/F/D/W/T	-- <sup>4</sup>	2/F/D/W/T	241 (9.5) <sup>7</sup>	NA	-- <sup>5</sup>
Hoverlane	A3B <sup>3</sup>	1-17	B	12	C-130	70 300 (155,000)	6,000	28/F/B/W/T	-- <sup>4</sup>	11/F/B/W/T	71 (2.8) <sup>7</sup>	NA	-- <sup>5</sup>
(Continued)													

- <sup>1</sup> Values based on correlations between CBR and/or  $k$  or effective  $k$  and the backcalculated subgrade modulus.
- <sup>2</sup> Determined for the critical aircraft (see Table D1).
- <sup>3</sup> Used LOW (Low Volume Evaluation) computer program to compute subgrade CBR and APE (Airfield Pavement Evaluation) computer program to evaluate pavement.
- <sup>4</sup> The allowable gross load is less than the minimum take-off weight of the critical aircraft.
- <sup>5</sup> Was not calculated because feature was evaluated as a flexible pavement.
- <sup>6</sup> Reconstruction is recommended because the ISM is less than the lower limit of LOW.
- <sup>7</sup> An AC overlay is not recommended. UFC 3-260-02 (Headquarters, Departments of the Army, Navy, and the Air Force 2001b) requires that the surface be a rigid pavement.

Table D3 (Concluded)

Pavement Facility	Feature	Test Number or Station m (ft)	Type Traffic Area	Subgrade Strength <sup>1</sup> CBR, % or K, kPa/mm (psi/in.)	Design Aircraft <sup>2</sup>				Allowable Gross Load Mg (kips)	PCN	Theoretical Overlay Requirements, mm (in.)		
					Aircraft	Weight Kg (lb)	Passes	ACN			AC	PCC Partial Bond	PCC No Bond
Fixed-wing Facilities (Concluded)													
Transient Parking Ramp	A4B	1-6	B	28 (102)	C-130	70 300 (155,000)	6,000	33/R/C/W/T	50 (110)	22/R/C/W/T	NA	147 (5.8)	185 (7.3)
Charlie Parking Ramp	A5B	1-11	B	30 (109)	C-130	70 300 (155,000)	6,000	33/R/C/W/T	46 (102)	20/R/C/W/T	NA	165 (6.5)	203 (8.0)
	A6B	1-15	B	26 (95)	C-130	70 300 (155,000)	6,000	35/R/D/W/T	44 (97)	21/R/D/W/T	NA	175 (6.9)	213 (8.4)
Rotary-wing Facilities													
Taxiway B	T1A <sup>3</sup>	0+00-3+20 (0+00-10+50)	B	-- <sup>6</sup>	CH-47	22 700 (50,000)	50,000	12/F/D/W/T	-- <sup>4</sup>	1/F/D/W/T	-- <sup>6</sup>	-- <sup>6</sup>	-- <sup>6</sup>
Compass Rose Taxiway	T4B <sup>3</sup>	0+00-0+64 (0+00-2+10)	B	9	CH-47	22 700 (50,000)	50,000	9/F/B/W/T	-- <sup>4</sup>	4/F/B/W/T	48 (1.9)	NA	-- <sup>5</sup>
Alpha Lane	T5A <sup>3</sup>	0+00-8+23 (0+00-27+00)	B	9	CH-47	22 700 (50,000)	50,000	9/F/B/W/T	-- <sup>4</sup>	4/F/B/W/T	28 (1.1)	NA	-- <sup>5</sup>
Delta Parking Ramp	A7B	1-3	B	29 (106)	CH-47	22 700 (50,000)	50,000	11/R/C/W/T	24 (52)	11/R/C/W/T	NA	0 (0.0)	0 (0.0)
	A8B	1-5	B	24 (89)	CH-47	22 700 (50,000)	50,000	11/R/D/W/T	23 (50)	11/R/D/W/T	NA	0 (0.0)	0 (0.0)
	A9B	1-20	B	37 (136)	CH-47	22 700 (50,000)	50,000	11/R/C/W/T	35 (77)	17/R/C/W/T	NA	0 (0.0)	0 (0.0)
B East Parking Ramp	A10B	1-5	B	27 (101)	CH-47	22 700 (50,000)	50,000	11/R/C/W/T	23 (50)	11/R/C/W/T	NA	0 (0.0)	0 (0.0)
B West Parking Ramp	A11B	1-5	B	26 (95)	CH-47	22 700 (50,000)	50,000	11/R/D/W/T	21 (47)	10/R/D/W/T	NA	74 (2.9)	99 (3.9)
Compass Rose	A12B	1-3	B	27 (100)	CH-47	22 700 (50,000)	50,000	11/R/C/W/T	22 (48)	10/R/C/W/T	NA	71 (2.8)	97 (3.8)
Alpha Ramp	A13B	1-16	B	41 (150)	CH-47	22 700 (50,000)	50,000	11/R/C/W/T	24 (53)	11/R/C/W/T	NA	0 (0.0)	0 (0.0)
<sup>1</sup> Values based on correlations between CBR and/or k and the backcalculated subgrade modulus.													
<sup>2</sup> Determined for the critical aircraft (see Table D1).													
<sup>3</sup> Used LOW (Low Volume Evaluation) computer program to compute subgrade CBR and APE (Airfield Pavement Evaluation) computer program to evaluate pavement.													
<sup>4</sup> The allowable gross load is less than the minimum take-off weight of the critical aircraft.													
<sup>5</sup> Was not calculated because feature was evaluated as a flexible pavement.													
<sup>6</sup> Reconstruction is recommended because the ISM is less than the lower limit of LOW													

<sup>1</sup> Values based on correlations between CBR and/or k and the backcalculated subgrade modulus.

<sup>2</sup> Determined for the critical aircraft (see Table D1).

<sup>3</sup> Used LOW (Low Volume Evaluation) computer program to compute subgrade CBR and APE (Airfield Pavement Evaluation) computer program to evaluate pavement.

<sup>4</sup> The allowable gross load is less than the minimum take-off weight of the critical aircraft.

<sup>5</sup> Was not calculated because feature was evaluated as a flexible pavement.

<sup>6</sup> Reconstruction is recommended because the ISM is less than the lower limit of LOW.

**Table D4**  
**Summary of Pavement Classification Numbers**

Pavement Facility	Controlling Feature	PCN <sup>1</sup> Code Normal Non-Frost	PCN <sup>1</sup> Code Thaw-weakening
<b>Fixed-wing Facilities</b>			
Runway 13-31 Overrun	R1A	11/F/C/W/T	4/F/D/W/T
Runway 13-31	R3A	14/F/B/W/T	6/F/D/W/T
Taxiway C	T6A	8/F/B/W/T	3/F/D/W/T
Taxiway D	T3A	32/R/C/W/T	24/F/D/W/T
13 Warm-up	A1B	28/R/B/W/T	21/R/D/W/T
31 Warm-up	A2B	2/F/D/W/T	3/F/D/W/T
Hoverlane	A3B	11/F/B/W/T	2/F/D/W/T
Transient Parking Ramp	A4B	22/R/C/W/T	16/R/D/W/T
Charlie Parking Ramp	A6B	21/R/D/W/T	17/R/D/W/T
<b>Rotary-wing Facilities</b>			
Taxiway B	T1A	1/F/D/W/T	1/F/D/W/T
Compass Rose Taxiway	T4B	4/F/B/W/T	1/F/D/W/T
Alpha Lane	T5A	4/F/B/W/T	1/F/D/W/T
Delta Parking Ramp	A8B	11/R/D/W/T	9/R/D/W/T
B East Parking Ramp	A10B	11/R/C/W/T	8/R/D/W/T
B West Parking Ramp	A11B	10/R/D/W/T	8/R/D/W/T
Compass Rose	A12B	10/R/C/W/T	8/R/D/W/T
Alpha Ramp	A13B	11/R/C/W/T	8/R/D/W/T
<sup>1</sup> Table D5 describes the components of the PCN code.			

**Table D5**  
**PCN Five-Part Code**

PCN	Pavement Type	Subgrade Strength <sup>1</sup>	Tire Pressure <sup>2</sup>	Method of PCN Determination
Numerical value	R - rigid	A	W	T - technical evaluation
	F - flexible	B	X	U - using aircraft
		C	Y	
		D	Z	
<b><u><sup>1</sup>Code</u></b>	<b><u>Category</u></b>	<b><u>Flexible Pavement CBR, %</u></b>	<b><u>Rigid Pavement K, kPa/mm, (psi/in.)</u></b>	
A	High	< 13	< 108 (400)	
B	Medium	13 > CBR < 8	108 > K < 54 (400 > K < 200)	
C	Low	8 > CBR < 4	54 > K < 27 (200 > K < 100)	
D	Ultra-low	< 4	< 27 (< 100)	
<b><u><sup>2</sup>Code</u></b>	<b><u>Category</u></b>	<b><u>Tire Pressure, MPa (psi)</u></b>		
W	High	No limit		
X	Medium	1.0 - 1.5 (146 - 217)		
Y	Low	0.51 - 1.0 (73 - 145)		
Z	Ultra-low	0 - 0.5 (0 - 72)		



# **Appendix E**

## **Micro PAVER Output Summary**

---

```

Network ID      - Butts
Branch Name     - RUNWAY 13-31 Overrun
Branch Number   - R1A
Section Number  - 1      Family - DEFAULT
Section Length  - 500.00 LF
Section Width   - 75.00 LF
Section Area    - 37500.00 SF
=====

```

```

-----
Inspection Date: 5/18/02
Riding Quality :           Safety:           Drainage Cond.:
Shoulder Cond. :           Overall Cond.:       F.O.D.:
-----

```

```

PCI OF SECTION = 92                                RATING = EXCELLENT

```

```

TOTAL NUMBER OF SAMPLE UNITS = 5
NUMBER OF RANDOM SAMPLE UNITS SURVEYED = 5
NUMBER OF ADDITIONAL SAMPLE UNITS SURVEYED = 0
RECOMMENDED MINIMUM OF 5 RANDOM SAMPLE UNITS TO BE SURVEYED.
STANDARD DEVIATION OF PCI BETWEEN RANDOM UNITS SURVEYED = 0.36%

```

\*\*\* EXTRAPOLATED DISTRESS QUANTITIES FOR SECTION \*\*\*

DISTRESS-TYPE	SEVERITY	QUANTITY	DENSITY %	DEDUCT VALUE
48 L & T CR	LOW	772.00 (LF)	2.06	7.57

\*\*\* PERCENT OF DEDUCT VALUES BASED ON DISTRESS MECHANISM \*\*\*

LOAD	RELATED DISTRESSES =	.00 PERCENT DEDUCT VALUES.
CLIMATE/DURABILITY	RELATED DISTRESSES =	100.00 PERCENT DEDUCT VALUES.
OTHER	RELATED DISTRESSES =	.00 PERCENT DEDUCT VALUES.

```

-----
Inspection Date: 5/18/2002
Riding Quality :           Safety:           Drainage Cond.:
Shoulder Cond. :           Overall Cond.:       F.O.D.:
-----

PCI OF SECTION =    25                                RATING = VERY POOR

TOTAL NUMBER OF SAMPLE UNITS =      5
NUMBER OF RANDOM SAMPLE UNITS SURVEYED      =      5
NUMBER OF ADDITIONAL SAMPLE UNITS SURVEYED =      0
RECOMMENDED MINIMUM OF      5 RANDOM SAMPLE UNITS TO BE SURVEYED.
STANDARD DEVIATION OF PCI BETWEEN RANDOM UNITS SURVEYED = 10.7%

*** EXTRAPOLATED DISTRESS QUANTITIES FOR SECTION ***

DISTRESS-TYPE      SEVERITY      QUANTITY      DENSITY %      DEDUCT VALUE
41 ALLIGATOR CR      LOW      1410.00 (SF)      3.76      33.32
41 ALLIGATOR CR      MEDIUM      2530.00 (SF)      6.74      51.04
43 BLOCK CR      LOW      2997.00 (SF)      7.99      15.82
43 BLOCK CR      MEDIUM      5919.00 (SF)      15.78      27.23
48 L & T CR      LOW      1372.00 (LF)      3.66      11.70
48 L & T CR      MEDIUM      821.00 (LF)      2.19      16.48
50 PATCHING      LOW      67.00 (SF)      0.18      2.01
52 WEATH?RAVEL      LOW      37500.00 (SF)      100.00      26.34
53 RUTTING      LOW      940.00 (SF)      2.51      19.66
53 RUTTING      MEDIUM      2248.00 (SF)      5.99      38.09

*** PERCENT OF DEDUCT VALUES BASED ON DISTRESS MECHANISM ***

LOAD      RELATED DISTRESSES = 59.00 PERCENT DEDUCT VALUES.
CLIMATE/DURABILITY RELATED DISTRESSES = 41.00 PERCENT DEDUCT VALUES.
OTHER      RELATED DISTRESSES = 0.00 PERCENT DEDUCT VALUES.

```

```

Network ID      - Butts
Branch Name     - RUNWAY 13-31
Branch Number   - R3A
Section Number  - 1      Family - DEFAULT
Section Length  - 500.00 LF
Section Width   - 75.00 LF
Section Area    - 37500.00 SF

```

```

-----
Inspection Date: 5/18/2002
Riding Quality :          Safety:          Drainage Cond.:
Shoulder Cond. :          Overall Cond.:      F.O.D.:
-----

```

```

PCI OF SECTION = 14                                RATING = VERY POOR

```

```

TOTAL NUMBER OF SAMPLE UNITS = 5
NUMBER OF RANDOM SAMPLE UNITS SURVEYED = 5
NUMBER OF ADDITIONAL SAMPLE UNITS SURVEYED = 0
RECOMMENDED MINIMUM OF 5 RANDOM SAMPLE UNITS TO BE SURVEYED.
STANDARD DEVIATION OF PCI BETWEEN RANDOM UNITS SURVEYED = 2.2%

```

\*\*\* EXTRAPOLATED DISTRESS QUANTITIES FOR SECTION \*\*\*

DISTRESS-TYPE	SEVERITY	QUANTITY	DENSITY %	DEDUCT VALUE
41 ALLIGATOR CR	LOW	2774.00 (SF)	7.40	40.13
41 ALLIGATOR CR	MEDIUM	4580.00 (SF)	12.21	58.88
48 L & T CR	LOW	1298.00 (LF)	3.46	11.21
48 L & T CR	MEDIUM	959.00 (LF)	2.56	17.89
52 WEATH?RAVEL	LOW	37500.00 (SF)	100.00	26.34
53 RUTTING	LOW	1199.00 (SF)	3.20	20.98
53 RUTTING	MEDIUM	2667.00 (SF)	7.11	39.69

\*\*\* PERCENT OF DEDUCT VALUES BASED ON DISTRESS MECHANISM \*\*\*

```

LOAD          RELATED DISTRESSES = 74.00 PERCENT DEDUCT VALUES.
CLIMATE/DURABILITY RELATED DISTRESSES = 26.00 PERCENT DEDUCT VALUES.
OTHER         RELATED DISTRESSES = 0.00 PERCENT DEDUCT VALUES.

```

```

Network ID      - Butts
Branch Name     - RUNWAY 13-31
Branch Number   - R4A
Section Number  - 1      Family - DEFAULT
Section Length  - 2560.00 LF
Section Width   - 75.00 LF
Section Area    - 192000.00 SF

```

```

-----
Inspection Date: 5/18/2002
Riding Quality :          Safety:          Drainage Cond.:
Shoulder Cond. :          Overall Cond.:      F.O.D.:
-----

```

```

PCI OF SECTION = 22                                RATING = VERY POOR

```

```

TOTAL NUMBER OF SAMPLE UNITS = 25
NUMBER OF RANDOM SAMPLE UNITS SURVEYED = 10
NUMBER OF ADDITIONAL SAMPLE UNITS SURVEYED = 0
RECOMMENDED MINIMUM OF 7 RANDOM SAMPLE UNITS TO BE SURVEYED.
STANDARD DEVIATION OF PCI BETWEEN RANDOM UNITS SURVEYED = 8.3%

```

\*\*\* EXTRAPOLATED DISTRESS QUANTITIES FOR SECTION \*\*\*

DISTRESS-TYPE	SEVERITY	QUANTITY	DENSITY %	DEDUCT VALUE
41 ALLIGATOR CR	LOW	19483.00 (SF)	10.15	43.41
41 ALLIGATOR CR	MEDIUM	6813.00 (SF)	3.55	42.99
48 L & T CR	LOW	7808.00 (LF)	4.07	12.68
48 L & T CR	MEDIUM	6312.00 (LF)	3.29	20.48
52 WEATH?RAVEL	LOW	153436.00 (SF)	79.92	24.27
52 WEATH?RAVEL	MEDIUM	19180.00 (SF)	9.99	20.67
53 RUTTING	LOW	6859.00 (SF)	3.57	21.61
53 RUTTING	MEDIUM	3962.00 (SF)	2.06	29.34

\*\*\* PERCENT OF DEDUCT VALUES BASED ON DISTRESS MECHANISM \*\*\*

```

LOAD          RELATED DISTRESSES = 64.00 PERCENT DEDUCT VALUES.
CLIMATE/DURABILITY RELATED DISTRESSES = 36.00 PERCENT DEDUCT VALUES.
OTHER         RELATED DISTRESSES = 0.00 PERCENT DEDUCT VALUES.

```

```

Network ID      - Butts
Branch Name     - RUNWAY 13-31
Branch Number   - R5A
Section Number  - 1      Family - DEFAULT
Section Length  - 500.00 LF
Section Width   - 75.00 LF
Section Area    - 37500.00 SF

```

```

=====
-----
Inspection Date: 5/18/2002
Riding Quality :          Safety:          Drainage Cond.:
Shoulder Cond. :          Overall Cond.:      F.O.D.:
-----

```

```

PCI OF SECTION = 26                                RATING = POOR

```

```

TOTAL NUMBER OF SAMPLE UNITS = 5
NUMBER OF RANDOM SAMPLE UNITS SURVEYED = 5
NUMBER OF ADDITIONAL SAMPLE UNITS SURVEYED = 0
RECOMMENDED MINIMUM OF 5 RANDOM SAMPLE UNITS TO BE SURVEYED.
STANDARD DEVIATION OF PCI BETWEEN RANDOM UNITS SURVEYED = 1.7%

```

\*\*\* EXTRAPOLATED DISTRESS QUANTITIES FOR SECTION \*\*\*

DISTRESS-TYPE	SEVERITY	QUANTITY	DENSITY %	DEDUCT VALUE
41 ALLIGATOR CR	LOW	1881.00 (SF)	5.01	36.20
48 L & T CR	LOW	2473.00 (LF)	6.60	17.93
48 L & T CR	MEDIUM	1259.00 (LF)	3.36	20.72
52 WEATH?RAVEL	LOW	37500.00 (SF)	100.00	26.34
53 RUTTING	LOW	3679.00 (SF)	9.81	28.21
53 RUTTING	MEDIUM	1161.00 (SF)	3.11	32.45

\*\*\* PERCENT OF DEDUCT VALUES BASED ON DISTRESS MECHANISM \*\*\*

```

LOAD          RELATED DISTRESSES = 60.00 PERCENT DEDUCT VALUES.
CLIMATE/DURABILITY RELATED DISTRESSES = 40.00 PERCENT DEDUCT VALUES.
OTHER         RELATED DISTRESSES = 0.00 PERCENT DEDUCT VALUES.

```

```

Network ID      - Butts
Branch Name     - RUNWAY 13-31
Branch Number   - R6A
Section Number  - 1      Family - DEFAULT
Section Length  - 400.00 LF
Section Width   - 75.00 LF
Section Area    - 30000.00 SF

```

```

-----
Inspection Date: 5/18/2002
Riding Quality :          Safety:          Drainage Cond.:
Shoulder Cond. :          Overall Cond.:      F.O.D.:
-----

```

```

PCI OF SECTION = 33                                RATING = POOR

```

```

TOTAL NUMBER OF SAMPLE UNITS = 4
NUMBER OF RANDOM SAMPLE UNITS SURVEYED = 3
NUMBER OF ADDITIONAL SAMPLE UNITS SURVEYED = 0
RECOMMENDED MINIMUM OF 5 RANDOM SAMPLE UNITS TO BE SURVEYED.
STANDARD DEVIATION OF PCI BETWEEN RANDOM UNITS SURVEYED = 2.23%

```

\*\*\* EXTRAPOLATED DISTRESS QUANTITIES FOR SECTION \*\*\*

DISTRESS-TYPE	SEVERITY	QUANTITY	DENSITY %	DEDUCT VALUE
41 ALLIGATOR CR	LOW	2338.00 (SF)	7.79	40.67
43 BLOCK CR	LOW	959.00 (SF)	3.20	11.71
48 L & T CR	LOW	2558.00 (LF)	8.53	21.16
48 L & T CR	MEDIUM	1049.00 (LF)	3.50	21.18
52 WEATH?RAVEL	LOW	30000.00 (SF)	100.00	26.34
53 RUTTING	LOW	1559.00 (SF)	5.19	23.86

\*\*\* PERCENT OF DEDUCT VALUES BASED ON DISTRESS MECHANISM \*\*\*

```

LOAD          RELATED DISTRESSES = 45.00 PERCENT DEDUCT VALUES.
CLIMATE/DURABILITY RELATED DISTRESSES = 55.00 PERCENT DEDUCT VALUES.
OTHER         RELATED DISTRESSES = 0.00 PERCENT DEDUCT VALUES.

```

```

Network ID      - Butts
Branch Name     - RUNWAY 13-31
Branch Number   - R7A
Section Number  - 1      Family - DEFAULT
Slab Length     - 20.00 LF
Slab Width      - 18.75 LF
Number of Slabs - 39
=====

```

```

-----
Inspection Date: 5/18/2002
Riding Quality :          Safety:          Drainage Cond.:
Shoulder Cond. :          Overall Cond.:      F.O.D.:
-----

```

```

PCI OF SECTION = 93                                RATING = EXCELLENT

```

```

TOTAL NUMBER OF SAMPLE UNITS = 2
NUMBER OF RANDOM SAMPLE UNITS SURVEYED = 2
NUMBER OF ADDITIONAL SAMPLE UNITS SURVEYED = 0
RECOMMENDED MINIMUM OF 5 RANDOM SAMPLE UNITS TO BE SURVEYED.
STANDARD DEVIATION OF PCI BETWEEN RANDOM UNITS SURVEYED = 4.2%

```

\*\*\* EXTRAPOLATED DISTRESS QUANTITIES FOR SECTION \*\*\*

DISTRESS-TYPE	SEVERITY	QUANTITY	DENSITY %	DEDUCT VALUE
72 SHAT. SLAB	LOW	1 (SLABS)	3.03	7.34
73 SHRINKAGE CR	LOW	1 (SLABS)	3.03	0.86

\*\*\* PERCENT OF DEDUCT VALUES BASED ON DISTRESS MECHANISM \*\*\*

```

LOAD          RELATED DISTRESSES = 90.00 PERCENT DEDUCT VALUES.
CLIMATE/DURABILITY RELATED DISTRESSES = 0.00 PERCENT DEDUCT VALUES.
OTHER         RELATED DISTRESSES = 10.00 PERCENT DEDUCT VALUES.

```



```

Network ID      - Butts
Branch Name     - TAXIWAY Bravo
Branch Number   - T1A
Section Number  - 1      Family - DEFAULT
Section Length  - 1050.00 LF
Section Width   - 50.00 LF
Section Area    - 52500.00 SF
=====

```

```

-----
Inspection Date: 5/18/2002
Riding Quality :          Safety:          Drainage Cond.:
Shoulder Cond. :          Overall Cond.:          F.O.D.:
-----

```

```

PCI OF SECTION = 2                                RATING = FAILED

```

```

TOTAL NUMBER OF SAMPLE UNITS = 10
NUMBER OF RANDOM SAMPLE UNITS SURVEYED = 7
NUMBER OF ADDITIONAL SAMPLE UNITS SURVEYED = 0
RECOMMENDED MINIMUM OF 5 RANDOM SAMPLE UNITS TO BE SURVEYED.
STANDARD DEVIATION OF PCI BETWEEN RANDOM UNITS SURVEYED = 1.8%

```

\*\*\* EXTRAPOLATED DISTRESS QUANTITIES FOR SECTION \*\*\*

DISTRESS-TYPE	SEVERITY	QUANTITY	DENSITY %	DEDUCT VALUE
41 ALLIGATOR CR	HIGH	599.00 (SF)	1.15	37.68
43 BLOCK CR	HIGH	50946.00 (SF)	97.04	77.78
48 L & T CR	MEDIUM	172.00 (LF)	0.33	6.79
48 L & T CR	HIGH	30.00 (LF)	0.10	7.50
52 WEATH?RAVEL	HIGH	52500.00 (SF)	100.00	69.91
53 RUTTING	LOW	862.00 (SF)	1.64	17.54
53 RUTTING	MEDIUM	614.00 (SF)	1.17	25.37
53 RUTTING	HIGH	629.00 (SF)	1.20	35.56

\*\*\* PERCENT OF DEDUCT VALUES BASED ON DISTRESS MECHANISM \*\*\*

```

LOAD          RELATED DISTRESSES = 42.00 PERCENT DEDUCT VALUES.
CLIMATE/DURABILITY RELATED DISTRESSES = 58.00 PERCENT DEDUCT VALUES.
OTHER         RELATED DISTRESSES = .00 PERCENT DEDUCT VALUES.

```

```

Network ID      - Butts
Branch Name     - TAXIWAY Charlie          Slab Length    -    20.00 LF
Branch Number   - T2A                      Slab Width     -    20.00 LF
Section Number  - 1      Family - DEFAULT   Number of Slabs -    50
=====

```

```

-----
Inspection Date: 5/18/2002
Riding Quality :           Safety:         Drainage Cond.:
Shoulder Cond. :           Overall Cond.:   F.O.D.:
-----

```

```

PCI OF SECTION = 90                                RATING = EXCELLENT

```

```

TOTAL NUMBER OF SAMPLE UNITS = 3
NUMBER OF RANDOM SAMPLE UNITS SURVEYED = 2
NUMBER OF ADDITIONAL SAMPLE UNITS SURVEYED = 0
RECOMMENDED MINIMUM OF 3 RANDOM SAMPLE UNITS TO BE SURVEYED.
STANDARD DEVIATION OF PCI BETWEEN RANDOM UNITS SURVEYED = 6.3%

```

\*\*\* EXTRAPOLATED DISTRESS QUANTITIES FOR SECTION \*\*\*

DISTRESS-TYPE	SEVERITY	QUANTITY	DENSITY %	DEDUCT VALUE
73 SHRINKAGE CR	NA	3 (SLABS)	6.00	1.18
74 JOINT SPALL	LOW	20 (SLABS)	40.00	9.59
75 CORNER SPALL	LOW	2 (SLABS)	4.00	1.47

\*\*\* PERCENT OF DEDUCT VALUES BASED ON DISTRESS MECHANISM \*\*\*

```

LOAD          RELATED DISTRESSES = 0.00 PERCENT DEDUCT VALUES.
CLIMATE/DURABILITY RELATED DISTRESSES = 0.00 PERCENT DEDUCT VALUES.
OTHER         RELATED DISTRESSES = 100.00 PERCENT DEDUCT VALUES.

```

```

Network ID      - Butts
Branch Name     - TAXIWAY DELTA
Branch Number   - T3A
Section Number  - 1      Family - DEFAULT
Slab Length     - 20.00 LF
Slab Width      - 20.00 LF
Number of Slabs - 74
=====

```

```

-----
Inspection Date: 5/18/2002
Riding Quality :          Safety:      Drainage Cond.:
Shoulder Cond. :      Overall Cond.:      F.O.D.:
-----

```

```

PCI OF SECTION = 50                                RATING = FAIR

```

```

TOTAL NUMBER OF SAMPLE UNITS = 3
NUMBER OF RANDOM SAMPLE UNITS SURVEYED = 3
NUMBER OF ADDITIONAL SAMPLE UNITS SURVEYED = 0
RECOMMENDED MINIMUM OF 3 RANDOM SAMPLE UNITS TO BE SURVEYED.
STANDARD DEVIATION OF PCI BETWEEN RANDOM UNITS SURVEYED = 1.0%

```

\*\*\* EXTRAPOLATED DISTRESS QUANTITIES FOR SECTION \*\*\*

DISTRESS-TYPE	SEVERITY	QUANTITY	DENSITY %	DEDUCT VALUE
65 JT SEAL DAM	HIGH	74 (SLABS)	100.00	12.00
71 FAULTING	LOW	7 (SLABS)	10.00	8.38
73 SKRINKAGE CR	LOW	1 (SLABS)	1.67	.80
74 JOINT SPALL	LOW	41 (SLABS)	58.33	11.83
74 JOINT SPALL	MEDIUM	8 (SLABS)	11.67	8.83
74 JOINT SPALL	HIGH	6 (SLABS)	8.33	18.66
75 CORNER SPALL	LOW	23 (SLABS)	33.33	10.37
75 CORNER SPALL	MEDIUM	2 (SLABS)	3.33	2.32
75 CORNER SPALL	HIGH	1 (SLABS)	1.67	2.72

\*\*\* PERCENT OF DEDUCT VALUES BASED ON DISTRESS MECHANISM \*\*\*

LOAD	RELATED DISTRESSES =	0.00 PERCENT DEDUCT VALUES.
CLIMATE/DURABILITY	RELATED DISTRESSES =	16.00 PERCENT DEDUCT VALUES.
OTHER	RELATED DISTRESSES =	84.00 PERCENT DEDUCT VALUES.

```

Network ID      - Butts
Branch Name     - COMPASS ROSE TAXIWAY
Branch Number   - T4B
Section Number  - 1      Family - DEFAULT
Section Length  - 210.00 LF
Section Width   - 40.00 LF
Section Area    - 8400.00 SF
=====

```

```

-----
Inspection Date: 5/18/2002
Riding Quality :           Safety:      Drainage Cond.:
Shoulder Cond. :      Overall Cond.:      F.O.D.:
-----

```

```

PCI OF SECTION = 19                                RATING = VERY POOR

```

```

TOTAL NUMBER OF SAMPLE UNITS = 2
NUMBER OF RANDOM SAMPLE UNITS SURVEYED = 2
NUMBER OF ADDITIONAL SAMPLE UNITS SURVEYED = 0
RECOMMENDED MINIMUM OF 2 RANDOM SAMPLE UNITS TO BE SURVEYED.
STANDARD DEVIATION OF PCI BETWEEN RANDOM UNITS SURVEYED = 10.0%

```

\*\*\* EXTRAPOLATED DISTRESS QUANTITIES FOR SECTION \*\*\*

DISTRESS-TYPE	SEVERITY	QUANTITY	DENSITY %	DEDUCT VALUE
48 L & T CR	LOW	73.00 (LF)	0.87	4.70
48 L & T CR	MEDIUM	178.00 (LF)	2.12	16.21
48 L & T CR	HIGH	430.00 (LF)	5.12	41.54
52 WEATH?RAVEL	HIGH	8400.00 (SF)	100.00	69.91

\*\*\* PERCENT OF DEDUCT VALUES BASED ON DISTRESS MECHANISM \*\*\*

```

LOAD          RELATED DISTRESSES = .00 PERCENT DEDUCT VALUES.
CLIMATE/DURABILITY RELATED DISTRESSES = 100.00 PERCENT DEDUCT VALUES.
OTHER         RELATED DISTRESSES = 0.00 PERCENT DEDUCT VALUES.

```

```

Network ID      - Butts
Branch Name     - ALPHA LANE
Branch Number   - T5A
Section Number  - 1      Family - DEFAULT
Section Length  - 2700.00 LF
Section Width   - 75.00 LF
Section Area    - 202500.00 SF
=====

```

```

-----
Inspection Date: 5/18/2002
Riding Quality :          Safety:      Drainage Cond.:
Shoulder Cond. :      Overall Cond.:      F.O.D.:
-----

```

```

PCI OF SECTION = 5                                RATING = FAILED

```

```

TOTAL NUMBER OF SAMPLE UNITS = 27
NUMBER OF RANDOM SAMPLE UNITS SURVEYED = 12
NUMBER OF ADDITIONAL SAMPLE UNITS SURVEYED = 0
RECOMMENDED MINIMUM OF 5 RANDOM SAMPLE UNITS TO BE SURVEYED.
STANDARD DEVIATION OF PCI BETWEEN RANDOM UNITS SURVEYED = 0.0%

```

\*\*\* EXTRAPOLATED DISTRESS QUANTITIES FOR SECTION \*\*\*

DISTRESS-TYPE	SEVERITY	QUANTITY	DENSITY %	DEDUCT VALUE
43 BLOCK CR	HIGH	202500.00 (SF)	100.00	78.00
52 WEATH?RAVEL	HIGH	202500.00 (SF)	100.00	69.91

\*\*\* PERCENT OF DEDUCT VALUES BASED ON DISTRESS MECHANISM \*\*\*

```

LOAD          RELATED DISTRESSES = .00 PERCENT DEDUCT VALUES.
CLIMATE/DURABILITY RELATED DISTRESSES = 100.00 PERCENT DEDUCT VALUES.
OTHER         RELATED DISTRESSES = 0.00 PERCENT DEDUCT VALUES.

```

```

Network ID      - Butts
Branch Name     - TAXIWAY CHARLIE
Branch Number   - T6A
Section Number  - 1      Family - DEFAULT
Section Length  - 237.00 LF
Section Width   - 40.00 LF
Section Area    - 9480.00 SF
=====

```

```

-----
Inspection Date: 5/18/2002
Riding Quality :           Safety:           Drainage Cond.:
Shoulder Cond. :           Overall Cond.:           F.O.D.:
-----

```

```

PCI OF SECTION = 5                                RATING = FAILED

```

```

TOTAL NUMBER OF SAMPLE UNITS = 2
NUMBER OF RANDOM SAMPLE UNITS SURVEYED = 2
NUMBER OF ADDITIONAL SAMPLE UNITS SURVEYED = 0
RECOMMENDED MINIMUM OF 2 RANDOM SAMPLE UNITS TO BE SURVEYED.
STANDARD DEVIATION OF PCI BETWEEN RANDOM UNITS SURVEYED = 0.0%

```

\*\*\* EXTRAPOLATED DISTRESS QUANTITIES FOR SECTION \*\*\*

DISTRESS-TYPE	SEVERITY	QUANTITY	DENSITY %	DEDUCT VALUE
43 BLOCK CR	HIGH	9480.00 (SF)	100.00	78.36
52 WEATH?RAVEL	HIGH	9480.00 (SF)	100.00	69.91

\*\*\* PERCENT OF DEDUCT VALUES BASED ON DISTRESS MECHANISM \*\*\*

```

LOAD          RELATED DISTRESSES = .00 PERCENT DEDUCT VALUES.
CLIMATE/DURABILITY RELATED DISTRESSES = 100.00 PERCENT DEDUCT VALUES.
OTHER         RELATED DISTRESSES = 0.00 PERCENT DEDUCT VALUES.

```

```

Network ID      - Butts
Branch Name     - 13 WARM-UP RAMP      Slab Length    -    20.00 LF
Branch Number   - A1B                  Slab Width     -    20.00 LF
Section Number  - 1      Family - DEFAULT  Number of Slabs -    105
=====

```

```

-----
Inspection Date: 5/18/2002
Riding Quality :          Safety:      Drainage Cond.:
Shoulder Cond. :      Overall Cond.:      F.O.D.:
-----

```

```

PCI OF SECTION = 92                                RATING = EXCELLENT

```

```

TOTAL NUMBER OF SAMPLE UNITS = 5
NUMBER OF RANDOM SAMPLE UNITS SURVEYED = 5
NUMBER OF ADDITIONAL SAMPLE UNITS SURVEYED = 0
RECOMMENDED MINIMUM OF 5 RANDOM SAMPLE UNITS TO BE SURVEYED.
STANDARD DEVIATION OF PCI BETWEEN RANDOM UNITS SURVEYED = 2.5%

```

\*\*\* EXTRAPOLATED DISTRESS QUANTITIES FOR SECTION \*\*\*

DISTRESS-TYPE	SEVERITY	QUANTITY	DENSITY %	DEDUCT VALUE
74 JOINT SPALL	LOW	29 (SLABS)	27.45	7.51
75 CORNER SPALL	LOW	1 (SLABS)	1.00	0.30

\*\*\* PERCENT OF DEDUCT VALUES BASED ON DISTRESS MECHANISM \*\*\*

LOAD	RELATED DISTRESSES =	0.00 PERCENT DEDUCT VALUES.
CLIMATE/DURABILITY	RELATED DISTRESSES =	0.00 PERCENT DEDUCT VALUES.
OTHER	RELATED DISTRESSES =	100.00 PERCENT DEDUCT VALUES.

```

Network ID      - BUTTS
Branch Name     - 31 WAR-UP RAMP
Branch Number   - A2B
Section Number  - 1      Family - DEFAULT
Section Length  - 390.00 LF
Section Width   - 190.00 LF
Section Area    - 52250.00 SF
=====

```

```

-----
Inspection Date: 5/18/2002
Riding Quality :          Safety:          Drainage Cond.:
Shoulder Cond. :          Overall Cond.:          F.O.D.:
-----

```

```

PCI OF SECTION = 5                                RATING = FAILED

```

```

TOTAL NUMBER OF SAMPLE UNITS = 11
NUMBER OF RANDOM SAMPLE UNITS SURVEYED = 7
NUMBER OF ADDITIONAL SAMPLE UNITS SURVEYED = 0
RECOMMENDED MINIMUM OF 5 RANDOM SAMPLE UNITS TO BE SURVEYED.
STANDARD DEVIATION OF PCI BETWEEN RANDOM UNITS SURVEYED = 5.8%

```

\*\*\* EXTRAPOLATED DISTRESS QUANTITIES FOR SECTION \*\*\*

DISTRESS-TYPE	SEVERITY	QUANTITY	DENSITY %	DEDUCT VALUE
43 BLOCK CR	HIGH	52250.00 (SF)	100.00	78.38
52 WEATH/RAVEL	HIGH	52250.00 (SF)	100.00	69.91

\*\*\* PERCENT OF DEDUCT VALUES BASED ON DISTRESS MECHANISM \*\*\*

```

LOAD          RELATED DISTRESSES = .00 PERCENT DEDUCT VALUES.
CLIMATE/DURABILITY RELATED DISTRESSES = 100.00 PERCENT DEDUCT VALUES.
OTHER         RELATED DISTRESSES = .00 PERCENT DEDUCT VALUES.

```



```

Network ID      - BUTTS
Branch Name     - HOVERLANE
Branch Number   - A3B
Section Number  - 1      Family - DEFAULT
Section Length  - 1650.00 LF
Section Width   - 150.00 LF
Section Area    - 247500.00 SF
=====

```

```

-----
Inspection Date: 5/18/2002
Riding Quality :          Safety:      Drainage Cond.:
Shoulder Cond. :      Overall Cond.:      F.O.D.:
-----

```

```

PCI OF SECTION = 93                                RATING = EXCELLENT

```

```

TOTAL NUMBER OF SAMPLE UNITS = 49
NUMBER OF RANDOM SAMPLE UNITS SURVEYED = 8
NUMBER OF ADDITIONAL SAMPLE UNITS SURVEYED = 0
RECOMMENDED MINIMUM OF 5 RANDOM SAMPLE UNITS TO BE SURVEYED.
STANDARD DEVIATION OF PCI BETWEEN RANDOM UNITS SURVEYED = 1.6%

```

\*\*\* EXTRAPOLATED DISTRESS QUANTITIES FOR SECTION \*\*\*

DISTRESS-TYPE	SEVERITY	QUANTITY	DENSITY %	DEDUCT VALUE
48 L & T CR	LOW	4019.00 (LF)	1.62	6.43

\*\*\* PERCENT OF DEDUCT VALUES BASED ON DISTRESS MECHANISM \*\*\*

LOAD	RELATED DISTRESSES =	.00 PERCENT DEDUCT VALUES.
CLIMATE/DURABILITY	RELATED DISTRESSES =	100.00 PERCENT DEDUCT VALUES.
OTHER	RELATED DISTRESSES =	.00 PERCENT DEDUCT VALUES.

```

Network ID      - Butts
Branch Name     - TRANSIENT PARKING
Branch Number   - A4B
Section Number  - 1      Family - DEFAULT
Slab Length    - 12.50 LF
Slab Width     - 11.00 LF
Number of Slabs - 324
=====

```

```

-----
Inspection Date: 5/18/2002
Riding Quality :          Safety:      Drainage Cond.:
Shoulder Cond. :      Overall Cond.:      F.O.D.:
-----

```

```

PCI OF SECTION = 82                                RATING = VERY GOOD

```

```

TOTAL NUMBER OF SAMPLE UNITS = 16
NUMBER OF RANDOM SAMPLE UNITS SURVEYED = 9
NUMBER OF ADDITIONAL SAMPLE UNITS SURVEYED = 0
RECOMMENDED MINIMUM OF 5 RANDOM SAMPLE UNITS TO BE SURVEYED.
STANDARD DEVIATION OF PCI BETWEEN RANDOM UNITS SURVEYED = 9.5%

```

\*\*\* EXTRAPOLATED DISTRESS QUANTITIES FOR SECTION \*\*\*

DISTRESS-TYPE	SEVERITY	QUANTITY	DENSITY %	DEDUCT VALUE
63 LINEAR CR	LOW	9 (SLABS)	2.78	2.81
65 JT SEAL DAM	LOW	36 (SLABS)	11.00	2.00
65 JT SEAL DAM	HIGH	288 (SLABS)	89.00	12.00
67 LARGE PATCH	MEDIUM	4 (SLABS)	1.11	3.05
67 LARGE PATCH	HIGH	4 (SLABS)	1.11	4.01
68 POPOUTS	LOW	2 (SLABS)	1.00	0.90
73 SHRINKAGE CR	LOW	4 (SLABS)	1.11	0.70
74 JOINT SPALL	LOW	2 (SLABS)	1.00	0.60
75 CORNER SPALL	LOW	4 (SLABS)	1.11	0.42
75 CORNER SPALL	MEDIUM	2 (SLABS)	1.00	1.20

\*\*\* PERCENT OF DEDUCT VALUES BASED ON DISTRESS MECHANISM \*\*\*

LOAD	RELATED DISTRESSES =	10.00 PERCENT DEDUCT VALUES.
CLIMATE/DURABILITY	RELATED DISTRESSES =	51.00 PERCENT DEDUCT VALUES.
OTHER	RELATED DISTRESSES =	39.00 PERCENT DEDUCT VALUES.

```

Network ID      - Butts
Branch Name     - CHARLIE PARKING
Branch Number   - A5B
Section Number  - 1      Family - DEFAULT
Slab Length     -      12.50 LF
Slab Width      -      11.00 LF
Number of Slabs -      990
=====

```

```

-----
Inspection Date: 5/18/2002
Riding Quality :          Safety:      Drainage Cond.:
Shoulder Cond. :      Overall Cond.:      F.O.D.:
-----

```

```

PCI OF SECTION =      84                      RATING = VERY GOOD

```

```

TOTAL NUMBER OF SAMPLE UNITS =      50
NUMBER OF RANDOM SAMPLE UNITS SURVEYED =      19
NUMBER OF ADDITIONAL SAMPLE UNITS SURVEYED =      0
RECOMMENDED MINIMUM OF 8 RANDOM SAMPLE UNITS TO BE SURVEYED.
STANDARD DEVIATION OF PCI BETWEEN RANDOM UNITS SURVEYED =      7.9%

```

\*\*\* EXTRAPOLATED DISTRESS QUANTITIES FOR SECTION \*\*\*

DISTRESS-TYPE	SEVERITY	QUANTITY	DENSITY %	DEDUCT VALUE
62 CORNER BREAK	MEDIUM	5 (SLABS)	1.00	1.50
63 LINEAR CR	LOW	2 (SLABS)	1.00	1.00
63 LINEAR CR	MEDIUM	2 (SLABS)	1.00	1.00
64 DURABIL. CR	LOW	19 (SLABS)	1.90	1.29
65 JT SEAL DAM	LOW	141 (SLABS)	14.29	2.00
65 JT SEAL DAM	HIGH	849 (SLABS)	85.71	12.00
66 SMALL PATCH	MEDIUM	2 (SLABS)	1.00	0.60
70 SCALING	LOW	7 (SLABS)	1.00	0.50
71 FAULTING	LOW	17 (SLABS)	1.67	2.06
71 FAULTING	MEDIUM	5 (SLABS)	1.00	2.00
73 SHRINKAGE CR	LOW	7 (SLABS)	1.00	0.60
74 JOINT SPALL	LOW	2 (SLABS)	1.00	0.60
74 JOINT SPALL	MEDIUM	12 (SLABS)	1.19	1.58
74 JOINT SPALL	HIGH	5 (SLABS)	1.00	3.00

\*\*\* PERCENT OF DEDUCT VALUES BASED ON DISTRESS MECHANISM \*\*\*

```

LOAD          RELATED DISTRESSES =      12.00 PERCENT DEDUCT VALUES.
CLIMATE/DURABILITY  RELATED DISTRESSES =      51.00 PERCENT DEDUCT VALUES.
OTHER         RELATED DISTRESSES =      37.00 PERCENT DEDUCT VALUES.

```

```

Network ID      - Butts
Branch Name     - CHARLIE PARKING
Branch Number   - A6B
Section Number  - 1      Family - DEFAULT
Slab Length     -      12.50 LF
Slab Width      -      11.00 LF
Number of Slabs -      1500
=====

```

```

-----
Inspection Date: 5/18/2002
Riding Quality :          Safety:      Drainage Cond.:
Shoulder Cond. :      Overall Cond.:      F.O.D.:
-----

```

```

PCI OF SECTION = 78                                RATING = VERY GOOD

```

```

TOTAL NUMBER OF SAMPLE UNITS = 64
NUMBER OF RANDOM SAMPLE UNITS SURVEYED = 21
NUMBER OF ADDITIONAL SAMPLE UNITS SURVEYED = 0
RECOMMENDED MINIMUM OF 8 RANDOM SAMPLE UNITS TO BE SURVEYED.
STANDARD DEVIATION OF PCI BETWEEN RANDOM UNITS SURVEYED = 7.5%

```

\*\*\* EXTRAPOLATED DISTRESS QUANTITIES FOR SECTION \*\*\*

DISTRESS-TYPE	SEVERITY	QUANTITY	DENSITY %	DEDUCT VALUE
62 CORNER BREAK	MEDIUM	4 (SLABS)	1.00	1.50
62 CORNER BREAK	HIGH	4 (SLABS)	1.00	3.00
63 LINEAR CR	LOW	14 (SLABS)	1.00	1.00
64 DURABIL. CR	LOW	14 (SLABS)	1.00	0.50
64 DURABIL. CR	MEDIUM	4 (SLABS)	1.00	1.00
64 DURABIL. CR	HIGH	4 (SLABS)	1.00	2.00
65 JT SEAL DAM	HIGH	1500 (SLABS)	100.00	12.00
66 SMALL PATCH	LOW	11 (SLABS)	1.00	0.15
67 LARGE PATCH	HIGH	7 (SLABS)	1.00	4.00
70 SCALING	LOW	148 (SLABS)	9.88	3.96
72 SHAT. SLAB	LOW	4 (SLABS)	1.00	2.50
73 SHRINKAGE CR	LOW	49 (SLABS)	3.29	0.88
74 JOINT SPALL	LOW	74 (SLABS)	4.94	2.13
74 JOINT SPALL	MEDIUM	11 (SLABS)	1.00	1.00
75 CORNER SPALL	LOW	32 (SLABS)	2.12	0.88
75 CORNER SPALL	MEDIUM	7 (SLABS)	1.00	0.80
75 CORNER SPALL	HIGH	4 (SLABS)	1.00	1.20

\*\*\* PERCENT OF DEDUCT VALUES BASED ON DISTRESS MECHANISM \*\*\*

```

LOAD          RELATED DISTRESSES = 21.00 PERCENT DEDUCT VALUES.
CLIMATE/DURABILITY  RELATED DISTRESSES = 40.00 PERCENT DEDUCT VALUES.
OTHER         RELATED DISTRESSES = 39.00 PERCENT DEDUCT VALUES..

```

Inspection Date: 5/18/2002		
Riding Quality :	Safety:	Drainage Cond.:
Shoulder Cond. :	Overall Cond.:	F.O.D.:

TOTAL NUMBER OF SAMPLE UNITS = 15  
NUMBER OF RANDOM SAMPLE UNITS SURVEYED = 12  
NUMBER OF ADDITIONAL SAMPLE UNITS SURVEYED = 0  
RECOMMENDED MINIMUM OF 5 RANDOM SAMPLE UNITS TO BE SURVEYED.  
STANDARD DEVIATION OF PCI BETWEEN RANDOM UNITS SURVEYED = 4.6%

DISTRESS-TYPE	SEVERITY	QUANTITY	DENSITY %	DEDUCT VALUE
62 CORNER BREAK	MEDIUM	3 (SLABS)	1.00	0.70
64 DURABIL. CR	HIGH	2 (SLABS)	1.00	2.00
65 JT SEAL DAM	HIGH	322 (SLABS)	100.00	12.00
70 SCALING	LOW	23 (SLABS)	5.88	2.46
71 FAULTING	LOW	3 (SLABS)	1.00	1.00
74 JOINT SPALL	LOW	26 (SLABS)	6.72	2.58
74 JOINT SPALL	MEDIUM	5 (SLABS)	1.26	1.74
75 CORNER SPALL	LOW	15 (SLABS)	3.78	1.39
75 CORNER SPALL	MEDIUM	3 (SLABS)	1.00	0.80



```

Network ID      - Butts
Branch Name    - DELTA PARKING
Branch Number  - A9B
Section Number - 1      Family - DEFAULT
Slab Length    -      18.00 LF
Slab Width     -      18.00 LF
Number of Slabs -      894
=====

```

```

-----
Inspection Date: 5/18/2002
Riding Quality :          Safety:      Drainage Cond.:
Shoulder Cond. :      Overall Cond.:      F.O.D.:
-----

```

```

PCI OF SECTION = 64                      RATING = GOOD

```

```

TOTAL NUMBER OF SAMPLE UNITS = 39
NUMBER OF RANDOM SAMPLE UNITS SURVEYED = 21
NUMBER OF ADDITIONAL SAMPLE UNITS SURVEYED = 0
RECOMMENDED MINIMUM OF 19 RANDOM SAMPLE UNITS TO BE SURVEYED.
STANDARD DEVIATION OF PCI BETWEEN RANDOM UNITS SURVEYED = 15.6%

```

\*\*\* EXTRAPOLATED DISTRESS QUANTITIES FOR SECTION \*\*\*

DISTRESS-TYPE	SEVERITY	QUANTITY	DENSITY %	DEDUCT VALUE
63 LINEAR CR	LOW	4 (SLABS)	1.00	1.00
63 LINEAR CR	MEDIUM	8 (SLABS)	1.00	1.00
64 DURABIL. CR	LOW	6 (SLABS)	1.00	0.50
64 DURABIL. CR	HIGH	2 (SLABS)	1.00	2.00
65 JT SEAL DAM	MEDIUM	578 (SLABS)	64.68	7.00
65 JT SEAL DAM	HIGH	316 (SLABS)	35.32	12.00
71 FAULTING	LOW	18 (SLABS)	1.99	2.33
71 FAULTING	MEDIUM	20 (SLABS)	2.21	4.68
71 FAULTING	HIGH	4 (SLABS)	1.00	3.50
74 JOINT SPALL	LOW	233 (SLABS)	26.05	7.24
74 JOINT SPALL	MEDIUM	101 (SLABS)	11.26	8.56
74 JOINT SPALL	HIGH	28 (SLABS)	3.09	9.46
75 CORNER SPALL	LOW	75 (SLABS)	8.39	3.12
75 CORNER SPALL	MEDIUM	34 (SLABS)	3.75	2.65
75 CORNER SPALL	HIGH	30 (SLABS)	3.31	3.75

\*\*\* PERCENT OF DEDUCT VALUES BASED ON DISTRESS MECHANISM \*\*\*

```

LOAD          RELATED DISTRESSES = 3.00 PERCENT DEDUCT VALUES.
CLIMATE/DURABILITY RELATED DISTRESSES = 31.00 PERCENT DEDUCT VALUES.
OTHER         RELATED DISTRESSES = 66.00 PERCENT DEDUCT VALUES.

```

```

Network ID      - Butts
Branch Name     - B EAST PARKING
Branch Number   - A10B
Section Number  - 1      Family - DEFAULT
Slab Length    - 12.50 LF
Slab Width     - 11.00 LF
Number of Slabs - 390
=====

```

```

-----
Inspection Date: 5/18/2002
Riding Quality :          Safety:      Drainage Cond.:
Shoulder Cond. :      Overall Cond.:      F.O.D.:
-----

```

```

PCI OF SECTION = 84                                RATING = VERY GOOD

```

```

TOTAL NUMBER OF SAMPLE UNITS = 20
NUMBER OF RANDOM SAMPLE UNITS SURVEYED = 12
NUMBER OF ADDITIONAL SAMPLE UNITS SURVEYED = 0
RECOMMENDED MINIMUM OF 5 RANDOM SAMPLE UNITS TO BE SURVEYED.
STANDARD DEVIATION OF PCI BETWEEN RANDOM UNITS SURVEYED = 5.5%

```

\*\*\* EXTRAPOLATED DISTRESS QUANTITIES FOR SECTION \*\*\*

DISTRESS-TYPE	SEVERITY	QUANTITY	DENSITY %	DEDUCT VALUE
65 JT SEAL DAM	HIGH	390 (SLABS)	100.00	12.00
71 FAULTING	LOW	5 (SLABS)	1.25	1.54
71 FAULTING	MEDIUM	2 (SLABS)	1.00	2.00
71 FAULTING	HIGH	2 (SLABS)	1.00	3.50
74 JOINT SPALL	LOW	11 (SLABS)	2.92	1.71
75 CORNER SPALL	LOW	5 (SLABS)	1.25	0.53

\*\*\* PERCENT OF DEDUCT VALUES BASED ON DISTRESS MECHANISM \*\*\*

```

LOAD          RELATED DISTRESSES = 0.00 PERCENT DEDUCT VALUES.
CLIMATE/DURABILITY RELATED DISTRESSES = 56.00 PERCENT DEDUCT VALUES.
OTHER         RELATED DISTRESSES = 44.00 PERCENT DEDUCT VALUES.

```



```

Network ID      - Butts
Branch Name     - B WEST PARKING
Branch Number   - AllB
Section Number  - 1      Family - DEFAULT
Slab Length     -      12.50 LF
Slab Width      -      11.00 LF
Number of Slabs -      390
=====

```

```

-----
Inspection Date: 5/18/2002
Riding Quality :          Safety:      Drainage Cond.:
Shoulder Cond. :      Overall Cond.:      F.O.D.:
-----

```

```

PCI OF SECTION =      85                      RATING = VERY GOOD

```

```

TOTAL NUMBER OF SAMPLE UNITS =      20
NUMBER OF RANDOM SAMPLE UNITS SURVEYED =      12
NUMBER OF ADDITIONAL SAMPLE UNITS SURVEYED =      0
RECOMMENDED MINIMUM OF 5 RANDOM SAMPLE UNITS TO BE SURVEYED.
STANDARD DEVIATION OF PCI BETWEEN RANDOM UNITS SURVEYED =  6.7%

```

\*\*\* EXTRAPOLATED DISTRESS QUANTITIES FOR SECTION \*\*\*

DISTRESS-TYPE	SEVERITY	QUANTITY	DENSITY %	DEDUCT VALUE
62 CORNER BK	LOW	2 (SLABS)	1.00	0.70
63 LINEAR CR	LOW	2 (SLABS)	1.00	1.00
65 JT SEAL DAM	MEDIUM	65 (SLABS)	16.67	7.00
65 JT SEAL DAM	HIGH	325 (SLABS)	83.33	12.00
72 SHAT. SLAB	MEDIUM	2 (SLABS)	1.00	5.00
73 SHRINKAGE CR	LOW	2 (SLABS)	1.00	0.60
74 JOINT SPALL	LOW	7 (SLABS)	1.67	1.36
74 JOINT SPALL	MEDIUM	3 (SLABS)	1.00	1.00
75 CORNER SPALL	LOW	3 (SLABS)	1.00	0.30

\*\*\* PERCENT OF DEDUCT VALUES BASED ON DISTRESS MECHANISM \*\*\*

```

LOAD          RELATED DISTRESSES =  23.00 PERCENT DEDUCT VALUES.
CLIMATE/DURABILITY  RELATED DISTRESSES =  66.00 PERCENT DEDUCT VALUES.
OTHER         RELATED DISTRESSES =  11.00 PERCENT DEDUCT VALUES.

```

```

Network ID      - Butts
Branch Name     - COMPASS ROSE
Branch Number   - A12B
Section Number  - 1      Family - DEFAULT
Slab Length    - 12.50 LF
Slab Width     - 12.50 LF
Number of Slabs - 64
=====

```

```

-----
Inspection Date: 5/18/2002
Riding Quality :          Safety:      Drainage Cond.:
Shoulder Cond. :      Overall Cond.:      F.O.D.:
-----

```

```

PCI OF SECTION = 84                                RATING = VERY GOOD

```

```

TOTAL NUMBER OF SAMPLE UNITS = 4
NUMBER OF RANDOM SAMPLE UNITS SURVEYED = 4
NUMBER OF ADDITIONAL SAMPLE UNITS SURVEYED = 0
RECOMMENDED MINIMUM OF 4 RANDOM SAMPLE UNITS TO BE SURVEYED.
STANDARD DEVIATION OF PCI BETWEEN RANDOM UNITS SURVEYED = 10.1%

```

\*\*\* EXTRAPOLATED DISTRESS QUANTITIES FOR SECTION \*\*\*

DISTRESS-TYPE	SEVERITY	QUANTITY	DENSITY %	DEDUCT VALUE
65 JT SEAL DAM	LOW	19 (SLABS)	25.00	2.00
65 JT SEAL DAM	HIGH	58 (SLABS)	75.00	12.00
71 FAULTING	LOW	1 (SLABS)	1.56	1.95
74 JOINT SPALL	LOW	1 (SLABS)	1.56	1.30
74 JOINT SPALL	HIGH	1 (SLABS)	1.56	5.09
75 CORNER SPALL	LOW	1 (SLABS)	1.56	0.69
75 CORNER SPALL	MEDIUM	1 (SLABS)	1.56	1.05

\*\*\* PERCENT OF DEDUCT VALUES BASED ON DISTRESS MECHANISM \*\*\*

```

LOAD          RELATED DISTRESSES = 0.00 PERCENT DEDUCT VALUES.
CLIMATE/DURABILITY RELATED DISTRESSES = 58.00 PERCENT DEDUCT VALUES.
OTHER         RELATED DISTRESSES = 42.00 PERCENT DEDUCT VALUES.

```

```

Network ID      - Butts
Branch Name    - ALPHA RAMP
Branch Number  - A13B
Section Number - 1      Family - DEFAULT
Slab Length    - 15.00 LF
Slab Width     - 15.00 LF
Number of Slabs - 2870
=====

```

```

-----
Inspection Date: 5/18/2002
Riding Quality :          Safety:      Drainage Cond.:
Shoulder Cond. :      Overall Cond.:      F.O.D.:
-----

```

```

PCI OF SECTION = 81                                RATING = VERY GOOD

```

```

TOTAL NUMBER OF SAMPLE UNITS = 136
NUMBER OF RANDOM SAMPLE UNITS SURVEYED = 30
NUMBER OF ADDITIONAL SAMPLE UNITS SURVEYED = 0
RECOMMENDED MINIMUM OF 17 RANDOM SAMPLE UNITS TO BE SURVEYED.
STANDARD DEVIATION OF PCI BETWEEN RANDOM UNITS SURVEYED = 11.1%

```

\*\*\* EXTRAPOLATED DISTRESS QUANTITIES FOR SECTION \*\*\*

DISTRESS-TYPE	SEVERITY	QUANTITY	DENSITY %	DEDUCT VALUE
62 CORNER BK	LOW	14 (SLABS)	1.00	0.70
62 CORNER BK	MEDIUM	5 (SLABS)	1.00	1.50
63 LINEAR CR	LOW	19 (SLABS)	1.00	1.00
64 DURABIL. CR	LOW	10 (SLABS)	1.00	0.50
66 SMALL PATCH	LOW	24 (SLABS)	1.00	0.15
70 SCALING	LOW	5 (SLABS)	1.00	0.50
71 FAULTING	LOW	148 (SLABS)	5.17	4.68
71 FAULTING	MEDIUM	14 (SLABS)	1.00	2.00
73 SHRINKAGE CR	LOW	139 (SLABS)	4.83	1.05
74 JOINT SPALL	LOW	483 (SLABS)	16.83	5.24
74 JOINT SPALL	MEDIUM	139 (SLABS)	4.83	4.27
74 JOINT SPALL	HIGH	5 (SLABS)	1.00	3.00
75 CORNER SPALL	LOW	411 (SLABS)	14.33	5.26
75 CORNER SPALL	MEDIUM	38 (SLABS)	1.33	0.93
75 CORNER SPALL	HIGH	10 (SLABS)	1.00	1.20

\*\*\* PERCENT OF DEDUCT VALUES BASED ON DISTRESS MECHANISM \*\*\*

```

LOAD          RELATED DISTRESSES = 10.00 PERCENT DEDUCT VALUES.
CLIMATE/DURABILITY RELATED DISTRESSES = 2.00 PERCENT DEDUCT VALUES.
OTHER         RELATED DISTRESSES = 88.00 PERCENT DEDUCT VALUES.

```

REPORT DOCUMENTATION PAGE				Form Approved OMB No. 0704-0188	
Public reporting burden for this collection of information is estimated to average 1 hour per response, including the time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing this collection of information. Send comments regarding this burden estimate or any other aspect of this collection of information, including suggestions for reducing this burden to Department of Defense, Washington Headquarters Services, Directorate for Information Operations and Reports (0704-0188), 1215 Jefferson Davis Highway, Suite 1204, Arlington, VA 22202-4302. Respondents should be aware that notwithstanding any other provision of law, no person shall be subject to any penalty for failing to comply with a collection of information if it does not display a currently valid OMB control number. <b>PLEASE DO NOT RETURN YOUR FORM TO THE ABOVE ADDRESS.</b>					
1. REPORT DATE (DD-MM-YYYY) April 2003 (Revised)		2. REPORT TYPE Final report		3. DATES COVERED (From - To)	
4. TITLE AND SUBTITLE  Airfield Pavement Evaluation, Butts Army Airfield, Fort Carson, Colorado				5a. CONTRACT NUMBER	
				5b. GRANT NUMBER	
				5c. PROGRAM ELEMENT NUMBER	
6. AUTHOR(S)  Robert W. Grau, Patrick S. McCaffrey, Jr., Dan D. Mathews				5d. PROJECT NUMBER	
				5e. TASK NUMBER	
				5f. WORK UNIT NUMBER MIPR2AJEAMEN04	
7. PERFORMING ORGANIZATION NAME(S) AND ADDRESS(ES)  U.S. Army Engineer Research and Development Center Geotechnical and Structures Laboratory 3909 Halls Ferry Road Vicksburg, MS 39180-6199				8. PERFORMING ORGANIZATION REPORT NUMBER  ERDC/GSL SR-03-3	
9. SPONSORING / MONITORING AGENCY NAME(S) AND ADDRESS(ES)  Funding Agency: U.S. Army Forces Command ATTN: AFEN-PR (Carole Jones) Fort McPherson, Georgia 30330-1062				10. SPONSOR/MONITOR'S ACRONYM(S)	
				11. SPONSOR/MONITOR'S REPORT NUMBER(S)	
12. DISTRIBUTION / AVAILABILITY STATEMENT Distribution limited to U.S. Government agencies only; test and evaluation; April 2003. Other requests for this document must be referred to Headquarters, U.S. Army Corps of Engineers (CECW-EW), Washington, DC 20314-1000.					
13. SUPPLEMENTARY NOTES					
14. ABSTRACT  An airfield pavement evaluation was performed in May 2002 at Butts Army Airfield, Fort Carson, Colorado, to develop information pertaining to the structural adequacy of the airfield pavements for continued use under its current mission and the upgrading of the pavements for mission changes. The pavement surface condition was evaluated using the Pavement Condition Index (PCI) survey procedure, and a nondestructive evaluation procedure was used to determine the load-carrying capability of the pavements and overlay requirements for continued use of the pavements under current missions. Results of the evaluation are presented including: (a) a tabulation of the existing pavement features, (b) the results of the nondestructive tests performed using a heavy weight deflectometer, (c) the PCI and rating of the surface of each pavement feature, (d) a structural evaluation and overlay requirements for 6,000 passes of the C-130 aircraft on the fixed-wing pavements and 50,000 passes of the CH-47 aircraft on the rotary-wing pavements, (e) the pavement classification number for each pavement facility, and (f) maintenance and repair recommendations based on the structural evaluation and condition survey.					
15. SUBJECT TERMS Aircraft classification number      Nondestructive testing Allowable gross aircraft load      Pavement classification number Butts Army Airfield      Pavement condition index					
16. SECURITY CLASSIFICATION OF:			17. LIMITATION OF ABSTRACT	18. NUMBER OF PAGES  119	19a. NAME OF RESPONSIBLE PERSON
a. REPORT UNCLASSIFIED	b. ABSTRACT UNCLASSIFIED	c. THIS PAGE UNCLASSIFIED			19b. TELEPHONE NUMBER (include area code)